

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 1675B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER N/S	NOT NECESSARY	600.25	-
1	FRONT DOOR N/S	DENTED/WARPED	1,600.00	1,462.00
1	FRONT DOOR LOCK	NOT NECESSARY	285.00	-
1	FRONT DOOR OUTER HANDLE	NOT NECESSARY	233.00	-
1	FRONT DOOR RUBBER	NECESSARY	197.00	197.00
1	FRONT DOOR SIDE MIRROR	NOT NECESSARY	1,085.00	-
1	ROCKER PANEL SIDE SKIRT N/S	DEFORMED/TORN	855.00	680.00
1	REAR DOOR -RH	TO REPAIR SEE LABOUR	1,655.00	-
1	REAR DOOR LOCK	NOT NECESSARY	289.20	-
1	REAR DOOR REGULATOR	NOT NECESSARY	240.00	-
1	REAR DOOR REGULATOR MOTOR	NOT NECESSARY	319.90	-
1	REAR DOOR RUBBER	NOT NECESSARY	153.30	-
	LESS 5% DISCOUNT		-375.63	-116.95
			7,137.02	2,222.05
	LABOUR			
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING.	NOT NECESSARY	80.00	-
	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.		400.00	60.00
	TO APPLY UNDERCOATING.		150.00	30.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR DOOR -RH.		1,500.00	500.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,400.00	1,000.00
			3,530.00	1,590.00
	GRAND TOTAL		10,667.02	3,812.05
	DECOMMENDED COST OF LUMP CUM DEPAIDS		_	2 000 00

RECOMMENDED COST OF LUMP SUM REPAIRS	3,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMO22003667/Uqy3m4





Report Ref No. CS/SMO22003667/Uqy3m4

CHUA KANG SENG
Licensed Appraiser