

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003670/KVY3N2**Date:** 24/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00005212201	
Claimant Vehicle No :	SMY8550R	Insured Vehicle No :	GBD5818E	
Date of Loss:	11/04/2022	Nature of Claim:	TP	Claim No: SNM22D202513/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY8550R		Engine No:	27492030892453
Make & Model:	MERCEDES-BENZ E250, 2.0 EXCLUSIVE (R18 LED) (A)		Chassis No:	WDD2130452A162718
Reg. Date:	01/03/2017 (Man. Year: 2016)		Odometer:	112980 km
Colour:	Metallic Dark Blue			
Engine Capacity:	1991 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R19	Rear Tyre Size:	275/35R19
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,002.47	2,550.24	2,452.23	49.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	515.00	735.00	58.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,252.47	3,065.24	3,187.23	50.98

INSPECTION

Date of Assignment:	20/04/2022	
Date Inspected:	25/04/2022	Inspected At: Cheong Cheong Motor Service Pte Ltd (HQ) Block 5032, Ang Mo Kio, Park 2, #01-293 Singapore 569535
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2022)
Parts:	143	MERCEDES-BENZ E250 2.0 EXCLUSIVE (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMY8550R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Cracked	2,246.20 FL	*2,072.80 FL
2	1		*REAR BUMPER REVERSE SENSOR	Serviceable	1,180.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	775.00 FL	*- FL
4	1		*REAR BUMPER SPONGE	Serviceable	295.00 FL	*- FL
5	1		*REAR BUMPER LOWER GARNISH	Dented/Cut	786.30 FL	*485.00 FL
6	1		*REAR BUMPER LOWER GARNISH CHROME	Cracked	275.80 FL	*275.80 FL
					Sub Total (\$\$)	5,558.30 2,833.60
					- List Item Discount on L Items 10.00/10.00% (\$\$)	555.83 283.36
					Total Parts (\$\$)	5,002.47 2,550.24

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR & REFIT THE SAME	New	50.00	15.00
2	TO RESENT & PROGRAM ON THE RESTRAINT SYSTEM	New	200.00	0.00
3	TO REMOVE,RENEW & REFIT ALL ACCIDENT DAMAGE PARTS & STRAIGHTEN ALL ACCIDENT DAMAGE AREAS & FIT THE ABOVE SAME	New	500.00	250.00
4	TO PUTTY & SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS & OTHER ACCIDENT AFFECTED AREAS	New	500.00	250.00
Gross Labour Cost (\$\$)			1,250.00	515.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >