



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGW 6779T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE	BENT	624.00	624.00
1	REAR BUMPER	DEFORMED	398.00	398.00
1	REAR TAILLAMPS (RIGHT SIDE)	CRACKED	388.00	388.00
1	TAILGATE WEATHER STRIP	NOT NECESSARY	375.00	-
1	TAILGATE LOCK	NOT NECESSARY	289.00	-
1	REAR BUMPER SIDE RETAINERS	DEFORMED	84.50	84.50
1	REAR BUMPER SIDE SEAL	NECESSARY	98.70	98.70
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	389.00	-
8	REAR BUMPER CLIP @ \$4.00	NECESSARY	32.00	32.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	385.20	-
1	REAR WINDSCREEN SEALANT	NECESSARY	80.00	80.00
	LESS 25% DISCOUNT		-	-426.30
			3,143.40	1,278.90
	<u>LABOUR</u>			
	LABOUR (WINDSCREEN) - SUPPLY LABOUR TO REPLACE WINDSCREEN TO NEW TAILGATE.		150.00	120.00
	LABOUR (GENERAL) - SUPPLY LABOUR TO REMOVE AND REPLACE ITEM(S). INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00	500.00
	RE-SPRAYING WORK (EXTERIOR ONLY) - INCLUSIVE OF LABOUR TO ADJUST REAR LEFT AND RIGHT FENDER. SPRAY WORK FOR REAR TAILGATE AND REAR BUMPER.		650.00	500.00
			1,400.00	1,120.00
	GRAND TOTAL		4,543.40	2,398.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CS/AGI22003672/Tvy3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.