



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 6977Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT RH BUMPER	BROKEN	1,550.00	1,550.00
1	FRONT RH BUMPER BRACKET	DENTED	385.00	385.00
1	FRONT RH HEADLAMP	BROKEN	1,750.00	1,500.00
1	FRONT RH HEADLAMP STRUCTURE	BENT	730.00	500.00
1	FRONT RH SMALL COMPARTMENT COVER PANEL	DENTED	1,300.00	1,300.00
1	FRONT PANEL	BROKEN	3,800.00	3,500.00
	LESS 10% DISCOUNT		-	-873.50
			9,515.00	7,861.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT WINDSCREEN MOULDING (SN)	NECESSARY	680.00	680.00
8	SEALANT @\$40.00 (SN)	NECESSARY	320.00	320.00
1	ERP (SN)	NECESSARY	26.00	26.00
			1,026.00	1,026.00
	<b><u>LABOUR</u></b>			
	LABOUR TO REMOVE FRONT WINDSCREEN TO ASSIST REPAIR.		1,000.00	1,000.00
	LABOUR CHARGES.		1,500.00	1,200.00
	CHECK WIRING.		50.00	30.00
	SPRAY PAINTING WITH DESIGN AND MULTI COLORS.		1,500.00	1,200.00
			4,050.00	3,430.00
	<b>GRAND TOTAL</b>		<b>14,591.00</b>	<b>12,317.50</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>9,050.00</b>

Report Ref No. CS/AGI22003673/Eqy3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.