



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 8898S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP ASSEMBLY	SCRATCHED	1,892.30	1,892.30
2	HEADLAMP LOWER BRACKET	NOT NECESSARY	98.30	-
1	FRONT GRILLE BASE	NOT NECESSARY	374.60	-
1	FRONT GRILLE CHROME MOULDING	SCRATCHED	422.00	374.90
1	FRONT BUMPER LOWER CHROME	NOT NECESSARY	162.30	-
1	FRONT GRILLE LOGO	NOT NECESSARY	62.00	-
1	SET FRONT GRILLE CLIPS	NOT NECESSARY	32.00	-
1	FRONT BUMPER	DEFORMED / TORN	822.00	620.50
2	FRONT BUMPER SIDE RETAINER @\$72.00	N/S BENT	144.00	35.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	413.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	40.00	35.00
1	FRONT BUMPER GRILLE	NOT NECESSARY	164.40	-
1	FRONT BUMPER FOG LAMP GARNISH	SCRATCHED	107.20	107.20
1	FRONT BUMPER DAY LIGHT	NOT NECESSARY	584.00	-
1	FRONT BUMPER SENSOR	SHORTED	168.20	168.20
1	FRONT BONNET	NOT NECESSARY	725.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	140.80	-
2	FRONT BONNET HINGES-L/R	NOT NECESSARY	191.20	-
1	FRONT BONNET SEAL	NOT NECESSARY	95.00	-
1	FRONT BONNET INSULATOR	NOT NECESSARY	285.60	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	480.20	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	250.75	-
1	FRONT SUPPORT PANEL CENTRE BRACKET	NOT NECESSARY	154.80	-
1	FRONT FENDER L/H	NOT NECESSARY	525.60	-
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	221.60	-
	LESS 20% DISCOUNT		-1,711.37	-646.62
			6,845.48	2,586.48
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LICENSE PLATE (SN)	NOT NECESSARY	40.00	-
10	FRONT BUMPER CLIPS @\$5.00 (SN)	REPEATED	50.00	-

Report Ref No. CS/AGI22003676/Uvy3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
10	FRONT FENDER INNER CLIPS @\$5.00 (SN) <u>LABOUR</u> TO REMOVE AND REPLACED DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL. TO RESPRAY REPLACED AND AFFECTED PANELS. TO CARRY OUT ANTI RUST TREATMENT. TO CHECK WIRING FOR PROPER FUNCTION. } TO CHECK ADJUST HEADLAMP HEIGHT. }	NOT NECESSARY	50.00	-
			140.00	-
		NOT NECESSARY	1,000.00	400.00
			850.00	500.00
			100.00	-
			100.00	50.00
			100.00	-
	2,150.00	950.00		
GRAND TOTAL			9,135.48	3,536.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CS/AGI22003676/Uvy3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.