

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R					
	Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CS/TPS22003682/Uvy3e2	
	C/O TOPLIS AND 133 CECIL STREE SINGAPORE 0695	HARDING (S) PTE LTD T #17-01A KECK SENG TOWER 35		Date:	02/08/2022	
				Code:		
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected		SMA 3008A	
	Policy No.	Y226205	Coverage (\$)		0.00	
	Claim No.	SNC22D200008	Excess (\$)		0.00	
	Assign From	VICTOR FONG	Assign Date		20/04/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	MAZDA 6	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JM6GL1071J0146283	Colour		GREY	
	Odometer	81608 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/55 R17	BRIDGESTONE		8 mm	
	L/H Front Tyre	225/55 R17	BRIDGESTONE		8 mm	
	R/H Rear Tyre	225/55 R17	BRIDGESTONE		8 mm	
	L/H Rear Tyre	225/55 R17	BRIDGESTONE		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE WHOLE VEHICLE. THE CAUSE OF DAMAGE DUE TO AFFECTED BY FINE SPRAY PAINTING DROPLETS.					
_	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	21/03/2022	Inspection Dat	<u>e</u>	28/04/2022	
	Survey held at	TRANS EUROKARS PTE LTD				
		NO 5 UBI CLOSE SINGAPORE 408605				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
		-				

13 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: