



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JSL 2358

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	YAMAHA FRONT SUSPENSION (LEFT)	SERVICEABLE	900.00	-
1	YAMAHA FRONT SUSPENSION (RIGHT)	SERVICEABLE	900.00	-
1	YAMAHA TRIPLE CLAMP (TOP)	TO REPAIR SEE LABOUR	220.00	-
1	YAMAHA TRIPLE CLAMP (BOTTOM)	SERVICEABLE	300.00	-
1	YAMAHA STEERING CONE BEARING	SERVICEABLE	110.00	-
1	YAMAHA FRONT WHEEL SHAFT	TO REPAIR SEE LABOUR	120.00	-
2	YAMAHA FRONT WHEEL BEARING	SERVICEABLE	80.00	-
2	YAMAHA FRONT WHEEL SEAL	SERVICEABLE	30.00	-
1	YAMAHA FRONT RIM	SERVICEABLE	460.00	-
1	YAMAHA ENGINE COVER (LEFT)	GRAZED	260.00	260.00
1	YAMAHA ENGINE COVER GASKET (LEFT)	NECESSARY	45.00	45.00
1	YAMAHA FRONT HEADLIGHT	GRAZED / CRACKED	380.00	380.00
1	YAMAHA CLUTCH CABLE	INTACT	45.00	-
1	YAMAHA CLUTCH LEVER HOLDER	INTACT	45.00	-
1	YAMAHA CLUTCH LEVER HOLDER SCREW	INTACT	10.00	-
1	YAMAHA SIDE STAND	GRAZED / BENT	55.00	55.00
1	YAMAHA GEAR SHIFTER + RUBBER	NECESSARY	65.00	65.00
1	YAMAHA GEAR SHIFTER TIE ROD	DISTORTED	20.00	20.00
1	YAMAHA GEAR SHIFTER ARM	DISTORTED	20.00	20.00
1	YAMAHA RIDER FOOTREST BRACKET (LEFT)	GRAZED	85.00	85.00
1	YAMAHA RIDER FOOTREST (LEFT)	GRAZED	25.00	25.00
1	YAMAHA RIDER FOOTREST HOLDER (U-HOLDER)	NECESSARY	20.00	20.00
1	YAMAHA RIDER FOOTREST SPRING (LEFT)	NECESSARY	15.00	15.00
1	YAMAHA RIDER FOOTREST EXTENDER SCREW (LEFT)	NECESSARY	10.00	10.00
2	YAMAHA PILLION FOOTRESTS	GRAZED	50.00	50.00
2	YAMAHA PILLION FOOTREST PINS	NECESSARY	30.00	30.00
2	YAMAHA PILLION FOOTREST }	GRAZED / BROKEN (1PC ONLY)	170.00	100.00
2	YAMAHA PILLION FOOTREST BRACKETS }	GRAZED / BROKEN (1PC ONLY)	170.00	-

Report Ref No. CS3/AWA21008183/Vvy3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET YAMAHA FRONT SIGNAL LIGHT	BROKEN (LEFT)	90.00	90.00
1	YAMAHA REAR LIGHT	BROKEN	360.00	360.00
1	YAMAHA FRONT BRAKE MASTER CYLINDER	INTACT	150.00	-
1	YAMAHA FRONT MUDGUARD	GRAZED	180.00	180.00
1	YAMAHA INNER CENTER FAIRING	CRACKED	280.00	280.00
1	YAMAHA REAR CENTER TAIL FAIRING (SMALL)	BROKEN	120.00	120.00
1	YAMAHA HEADFAIRING (CENTER)	GRAZED	220.00	220.00
1	YAMAHA HEAD COWL C/W WINDSHIELD	GRAZED	95.00	95.00
1	YAMAHA SIDE TAIL FAIRING (LEFT)	DISTORTED / SHIFTED	220.00	220.00
1	YAMAHA SIDE TAIL FAIRING (RIGHT)	CRACKED / GRAZED	220.00	220.00
1	YAMAHA HEADLIGHT BEHIND FAIRING - LEFT (MATTE BLACK)	GRAZED	150.00	150.00
1	SET YAMAHA FRONT SIDE FAIRING	GRAZED (LEFT)	700.00	350.00
1	YAMAHA FAIRING RIVETS / SCREWS	NECESSARY	20.00	20.00
1	YAMAHA REAR RIM	WARPED / WOBBLE	360.00	360.00
1	YAMAHA REAR SIGNAL LIGHTS	BROKEN	90.00	90.00
1	YAMAHA REAR NUMBER PLATE LIGHT	BROKEN	120.00	120.00
2	YAMAHA SIDE MIRRORS	BENT / SCRATCHED (1PC ONLY)	90.00	45.00
1	YAMAHA REAR NUMBER PLATE HOLDER	BROKEN	120.00	120.00
1	YAMAHA REAR SEAL LOWER GARNISH	CRACKED	75.00	75.00
1	YAMAHA SEAL	SERVICEABLE	180.00	-
	LESS 10% DISCOUNT		-	-429.50
			8,480.00	3,865.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	AKRAPOVIC EXHAUST MUFFLER (SN) (LOCAL REPAIR)	CRACKED / GRAZED / DENTED	800.00	200.00
1	AKRAPOVIC EXHAUST COVER (CARBON) (SN)	GRAZED	55.00	55.00
1	SET CNC FRONT BRAKE / CLUTCH LEVER (SN)	GRAZED	300.00	150.00
1	CNC FRAME SLIDER (LEFT) (SN)	GRAZED	120.00	60.00
1	REAR NUMBER PLATE (SN)	BENT / DENTED	20.00	20.00
			1,295.00	485.00

Report Ref No. CS3/AWA21008183/Vvy3e2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b> TO REMOVE & REPLACE FRONT RIM, FRONT WHEEL BEARING, AXLE SHAFT, TRIPPLE CLAMPS, FRONT FORK, STEERING CONE, FRONT BRAKE DISC. TO REMOVE & REPLACE ABOVE BODY DAMAGED PARTS, CHECK WIRING & LIGHTING SYSTEM. INCLUSIVE OF THE REPAIR OF YAMAHA TRIPLE CLAMP (TOP) AND YAMAHA FRONT WHEEL SHAFT. TO CONDUCT CHASSIS ALIGNMENT. TOWING-FROM TRAFFIC POLICE COMPOUND TO WORKSHOP.	NOT NECESSARY	300.00  650.00  600.00 60.00 1,610.00	-  250.00  50.00 60.00 360.00
<b>GRAND TOTAL</b>			<b>11,385.00</b>	<b>4,710.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,750.00</b>

Report Ref No. CS3/AWA21008183/Vvy3e2-1

THEVAN THOMAS KARTHIKESAVAN

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.