

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003686/KEA3Q2**Date:** 21/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800147926
Claimant Vehicle No :	SLX3301T	Insured Vehicle No :	SLV5009K
Date of Loss:	19/04/2022	Nature of Claim:	TP
		Claim No:	1639462872SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX3301T	Engine No:	2ARH597462
Make & Model:	TOYOTA ALPHARD, 2.5 X CVT (A)	Chassis No:	AGH300028534
Reg. Date:	23/03/2018 (Man. Year: 2015)	Odometer:	178014 km
Colour:	Metallic Black		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	SUNWIDE 8 mm	Rear Left Side:	Gremax 8 mm
Front Right Side:	SUNWIDE 8 mm	Rear Right Side:	Gremax 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,666.25	8,041.12	4,625.13	36.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	1,810.00	1,180.00	39.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,656.25	9,851.12	5,805.13	37.08
Approved Total (Overridden) (S\$)		7,900.00		
(S\$)	15,656.25	7,900.00	7,756.25	49.54
+ GST 7.00/7.00% (S\$)	1,095.94	553.00	542.94	49.54
Nett Amount (S\$)	16,752.19	8,453.00	8,299.19	49.54
+ Car Rental (9.0 x S\$170.00/day) (S\$)		1,530.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,985.00		
Global Sum Settlement (S\$)		9,980.00		

INSPECTION

Date of Assignment:	20/04/2022		
Date Inspected:	20/04/2022	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	855.00 FL	*855.00 FL
2	1		*FRONT BONNET HINGE LH	Repair	60.00 FL	*- FL
3	1		*FRONT BONNET HINGE RH	Distorted	60.00 FL	*60.00 FL
4	1		*FRONT HEADLAMP RH	Cracked	3,900.00 FL	*2,970.50 FL
5	1		*FRONT HEADLAMP CONTROL UNIT	Dented / Shorted	850.00 FL	*618.00 FL
6	1		*FRONT HEADLAMP UPPER PANEL RH	Buckled	365.00 FL	*313.00 FL
7	1		*FRONT GRILLE ASSY	Mtg Cracked	855.00 FL	*855.00 FL
8	1		*FRONT BUMPER	Torn	667.00 FL	*667.00 FL
9	1		*FRONT BUMPER SIDE BRACKET RH	Cracked	115.00 FL	*115.00 FL
10	1		*FRONT BUMPER TOWING COVER RH	Serviceable	30.00 FL	*- FL
11	1		*FRONT BUMPER PARKING SENSOR RH	Serviceable	488.00 FL	*- FL
12	1		*FRONT BUMPER FOG LAMP COVER RH	Serviceable	165.00 FL	*- FL
13	1		*FRONT BUMPER FOG LAMP RH	Mtg Cracked	290.00 FL	*290.00 FL
14	1		*FRONT BUMPER REINFORCEMENT	Repair	452.00 FL	*- FL
15	1		*FRONT BUMPER ABSORBER FOAM	Cracked	75.00 FL	*75.00 FL
16	1		*FRONT BUMPER LOWER GRILLE	Serviceable	215.00 FL	*- FL
17	1		*FRONT SUPPORT PANEL	Repair	580.00 FL	*- FL
18	1		*FRONT SUPPORT PANEL UPPER COVER	Serviceable	265.00 FL	*- FL
19	1		*FRONT FENDER RH	Bent	1,249.00 FL	*789.00 FL
20	1		*FRONT FENDER INNER SHIELD RH	Distorted	298.00 FL	*228.90 FL
21	1		*FRONT QUARTER GLASS WITH CHROME MOULDING RH	Dented	490.00 FL	*446.00 FL
22	1		*FRONT RIM RH (LOCAL REPAIR)	Scratched	1,279.50 FS	*150.00 FS
23	1		*FRONT ABSORBER RH	Bent	500.00 FL	*481.90 FL
24	1		*FRONT LOWER ARM RH	Distorted	815.00 FL	*585.20 FL
25	1		*FRONT KNUCKLE ARM RH	Bent	625.00 FL	*522.00 FL
26	1		*FRONT WHEEL BEARING RH	Necessary	585.00 FL	*410.00 FL
27	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
28	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*50.00 FS
29	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
30	1		*FRONT FENDER INNER SHIELD CLIPS RH	Necessary	40.00 FS	*40.00 FS
31	1		*FRONT QUARTER GLASS SEALANT RH	Necessary	60.00 FS	*30.00 FS
32	1		*FRONT SUPPORT PANEL UPPER COVER CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,378.50	10,611.50
- List Item Discount on L Items 25.00/25.00% (\$)	3,712.25	2,570.38
Total Parts (\$)	12,666.25	8,041.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE REPLACE ,REFIX ,REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	New	1,000.00	600.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET ,FRONT BUMPER ,FRONT FENDER RH ,FRONT DOOR RH & ETC	New	1,000.00	800.00
3	LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC	New	120.00	50.00
4	LABOUR CHARGES TO REMOVE & REPLACE FRONT FENDER QUARTER GLASS RH ,FRONT FENDER QUARTER GLASS SEALANT & ETC	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH ,FRONT LOWER ARM RH ,FRONT KNUCKLE ARM RH & ETC	New	250.00	180.00
6	TO WHEEL ALIGNMENT & BALANCING	New	80.00	20.00
7	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	150.00	0.00
8	TO TUFF KOTE & UNDERSEAL MATERIALS	New	150.00	80.00
9	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	120.00	20.00
Gross Labour Cost (\$)			2,990.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >