

ASS. REC. BY:

REF:

AIG/ 220036861ke

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3-6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLX 3301 T

Yr Regn:

03, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Alphard

c.c

2493

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

178014

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

AGH 30 - 0028534

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

Sunwide 215/60R16

R: Cremax

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

19/4/22

D.O.I.

20/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015/151

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/5 11:20 AM @ 79001 Carhu 20/5/22

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Date: 19/04/2022

Vehicle No: SLX3301T

Model: TOYOTA ALPHARD 2.5X CVT

Chassis: AGH300028534-2015

Reg.Year: 2018

Third Party Insurer: AIG

Third Party Veh No: SLV5009K

Date of Accident: 19/04/2022

Estimator: TING AN

Surveyor:

Not available
11 Sep @ 7900h
Murray Alan Paim
6 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		<i>R</i> \$855.00
2	FRONT BONNET HINGE LH	1		<i>R</i> \$60.00
3	FRONT BONNET HINGE RH	1		<i>DIY</i> \$60.00
4	FRONT HEADLAMP RH <i>2870.50</i>	1		<i>CM</i> \$3,900.00
5	FRONT HEADLAMP CONTROL UNIT <i>618</i>	1		<i>RediPharm</i> \$850.00
6	FRONT HEADLAMP UPPER PANEL RH <i>313</i>	1		<i>Ru</i> \$365.00
7	FRONT GRILLE ASSY	1		<i>mg CM</i> \$855.00
8	FRONT BUMPER	1		<i>Th</i> \$667.00
9	FRONT BUMPER SIDE BRACKET RH	1		<i>CM</i> \$115.00
10	FRONT BUMPER TOWING COVER RH	1		<i>Pr</i> \$30.00
11	FRONT BUMPER PARKING SENSOR RH	1		<i>Pr</i> \$488.00
12	FRONT BUMPER FOG LAMP COVER RH	1		<i>Pr</i> \$165.00
13	FRONT BUMPER FOG LAMP RH	1		<i>mg CM</i> \$290.00
14	FRONT BUMPER REINFORCEMENT	1		<i>R</i> \$452.00
15	FRONT BUMPER ABSORBER FOAM	1		<i>CM</i> \$75.00
16	FRONT BUMPER LOWER GRILLE	1		<i>Pr</i> \$215.00
17	FRONT SUPPORT PANEL	1		<i>R</i> \$580.00
18	FRONT SUPPORT PANEL UPPER COVER	1		<i>Pr</i> \$265.00
19	FRONT FENDER RH <i>789</i>	1		<i>R</i> \$1,249.00
20	FRONT FENDER INNER SHIELD RH <i>228.90</i>	1		<i>DIY</i> \$298.00
21	FRONT QUARTER GLASS WITH CHROME MOULDING RH	1	<i>446</i>	<i>Redi</i> \$490.00
22	FRONT RIM RH	1	<i>R</i> <i>SCR</i>	\$1,706.00
23	FRONT ABSORBER RH <i>481.90</i>	1		<i>R</i> \$500.00
24	FRONT LOWER ARM RH <i>585.20</i>	1		<i>DIY</i> \$815.00
25	FRONT KNUCKLE ARM RH <i>522</i>	1		<i>R</i> \$625.00
26	FRONT WHEEL BEARING RH <i>410</i>	1		<i>m</i> \$585.00
27	FRONT DOOR RH	1		REPAIR
SUB TOTAL				\$16,555.00
LESS 25%				-\$4,138.75
PARTS TOTAL				\$12,416.25

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19/04/2022
Vehicle No: SLX3301T
Model: TOYOTA ALPHARD 2.5X CVT
Chassis: AGH300028534-2015
Reg.Year: 2018

Third Party Insurer: AIG
Third Party Veh No: SLV5009K
Date of Accident: 19/04/2022
Estimator: TING AN
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT GRILLE CLIPS	1		mc \$50.00
2	FRONT BUMPER CLIPS	1		mc \$60.00
3	FRONT FENDER INNER SHIELD CLIPS RH	1		mc \$40.00
4	FRONT QUARTER GALSS SEALANT RH	1		mc \$60.00
5	FRONT SUPPORT PANEL UPPER COVER CLIPS	1		mc \$40.00
S/N TOTAL				\$250.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$1,000.00 600

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH & ETC.

\$1,000.00 800

LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC.

\$120.00 50

LABOUR CHARGES TO REMOVE & REPLACE FRONT FENDER QUARTER GLASS RH, FRONT FENDER QUARTER GLASS SEALANT & ETC.

\$120.00 60

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT LOWER ARM RH, FRONT KNUCKLE ARM RH & ETC.

\$250.00 180

TO WHEEL ALIGNMENT & BALANCING.

\$80.00 20

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

nn \$150.00 X

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$150.00 80

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$120.00 20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Fault" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL

\$2,990.00

TOTAL

\$15,656.25

TING AN

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011

