

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22003687/APA3Q2**Date:** 16/12/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210127973
<b>Claimant Vehicle No :</b>	GBH4565U	<b>Insured Vehicle No :</b>	GBL5811G
Date of Loss:	12/04/2022	Nature of Claim:	TP
		Claim No:	2912668038SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBH4565U</b>	Engine No:	YD25422393A
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M)	Chassis No:	JN1MC2E26Z0008657
Reg. Date:	06/06/2018 (Man. Year: 2017)	Odometer:	117588 km
Colour:	Grey		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,053.63	4,979.72	3,073.91	38.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	1,540.00	1,760.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,353.63</b>	<b>6,519.72</b>	<b>4,833.91</b>	<b>42.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,100.00</b>		
<b>(S\$)</b>	11,353.63	5,100.00	6,253.63	55.08
<b>+ GST 7.00/7.00% (S\$)</b>	794.75	357.00	437.75	55.08
<b>Nett Amount (S\$)</b>	<b>12,148.38</b>	<b>5,457.00</b>	<b>6,691.38</b>	<b>55.08</b>
<b>+ Loss of Use (8.0 x S\$95.00/day) (S\$)</b>		760.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>6,224.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>6,200.00</b>		

**INSPECTION**

Date of Assignment:	26/04/2022		
Date Inspected:	26/04/2022	Inspected At:	Mg Solution Pte Ltd - Kaki Bukit (HQ) 25 Kaki Bukit Road 4 #04-01 Singapore 41800
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIDE MIRROR ASSY	Damaged	520.80 FL	*520.80 FL
2	1		*FRONT SIDE MIRROR COVER	Repair	130.00 FL	*- FL
3	1		*FRONT DOOR LH	Not Necessary	1,533.50 FL	*- FL
4	1		*FRONT DOOR GLASS	Cut	520.80 FL	*385.00 FL
5	1		*SLIDING DOOR LH	Dented	1,688.50 FL	*1,325.00 FL
6	1		*REAR SIDE DOOR RAILING LH	Dented	345.60 FL	*345.60 FL
7	1		*REAR SIDE DOOR RAILING END LH	Not Necessary	56.80 FL	*- FL
8	1		*TAIL LAMP LH	Cut	374.40 FL	*374.40 FL
9	1		*REAR SIDE PANEL LH	Dented	2,855.30 FL	*1,793.00 FL
10	1		*REAR BUMPER	Torn	765.00 FL	*687.00 FL
11	1		*REAR BUMPER SIDE RETAINER	Necessary	80.00 FL	*80.00 FL
12	1		*FRONT DOOR COMPANY STICKER	Not Necessary	50.00 FS	*- FS
13	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,940.70</b>	<b>5,530.80</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	887.07	551.08
<b>Total Parts (\$)</b>	<b>8,053.63</b>	<b>4,979.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	800.00
3	WIRING CHECK	New	80.00	30.00
4	TO REMOVE AND REFIX SLIDING DOOR MECHANISM	New	120.00	60.00
5	TO REMOVE AND REFIX REAR REVERSE SENSOR	New	100.00	50.00
			<b>Gross Labour Cost (\$)</b>	<b>1,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >