



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 4439T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE BAR	BENT	114.40	114.40
1	SET HANDLE BALANCE	O/S CUT	50.00	25.00
1	BRAKE LEVER	BENT / CUT	38.00	38.00
1	FRONT BRAKE MASTER PUMP COMPLETE	CUT	425.50	425.50
1	SET MIRROR	O/S CUT	130.00	65.00
1	FRONT INDICATOR LIGHT RH	CUT	85.50	85.50
1	FRONT MUDGUARD (MAT BLACK)	TO REPAIR SEE LABOUR	105.00	-
1	FUEL TANK SIDE COVER RH	CRACKED	165.20	165.20
2	RIDER FOOTREST @\$68.00	O/S CUT	136.00	68.00
1	RIDER FOOTREST BRACKET RH	TO REPAIR SEE LABOUR	115.00	-
1	FRONT BRAKE PEDAL	CUT / BENT	65.00	65.00
1	EXHAUST PROTECTOR	GRAZED	118.50	118.50
1	EXHAUST MUFFLER CAP	SERVICEABLE	98.00	-
1	REAR MUDGUARD	NOT NECESSARY	125.80	-
1	REAR MUDGUARD SIDE REFLECTOR LH	CUT	58.00	58.00
1	REAR CHAIN COVER	TORN	106.90	106.90
	LESS 10% DISCOUNT		-193.68	-133.50
			1,743.12	1,201.50
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	CUT	20.00	10.00
1	REAR NUMBER PLATE (SN)	BENT	25.00	15.00
1	SET STEERING CONE & BEARING (SN)	NOT NECESSARY	180.00	-
1	SET FRONT FORK OIL SEAL & DUST COVER (SN)	NOT NECESSARY	160.00	-
4	LITS FRONT FORK HYDRAULIC FLUID (SN)	NOT NECESSARY	80.00	-
1	SET BODY STICKER (SN)	NECESSARY	100.00	50.00
1	SET REAR SWING ARM BUSHES (SN)	NOT NECESSARY	120.00	-
1	REAR TOP BOX (45L) (SN)	CUT	350.00	200.00
1	SET REAR BOX RACK WITH BASE (SN)	SERVICEABLE	180.00	-
			1,215.00	275.00

Report Ref No. CS3/ASM21010289/Vvy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TOWING (2 TRIPS).		150.00	60.00
	FRONT WHEEL BALANCE.	NOT NECESSARY	120.00	-
	REAR WHEEL BALANCE.	NOT NECESSARY	120.00	-
	FRONT FORK REPAIR & ALIGN.	NOT NECESSARY	400.00	-
	STEERING STEM REPAIR & ALIGN.	NOT NECESSARY	200.00	-
	REAR SWING ARM REPAIR & ALIGN.		350.00	150.00
	BODY FRAME ALIGNMENT.	NOT NECESSARY	450.00	-
	REMOVE & REPLACE ACCIDENT DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF FRONT MUDGUARD (MAT BLACK) AND RIDER FOOTREST BRACKET RH.		500.00	300.00
			2,290.00	510.00
	GRAND TOTAL		5,248.12	1,986.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CS3/ASM21010289/Vvy3e2-1

THEVAN THOMAS KARTHIKESAVAN

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.