

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003690/EQCE2

Date: 02/08/2022

REFERENCE

Insured/Claimant:	LOOI WING YEOW	Policy No:	1800093184		
Date of Loss:	14/04/2022	Nature of Claim:	OD	Claim No:	1553058231SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC206C		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK065315
Reg. Date:	03/08/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF52JA119536
Colour:	Brown	Odometer:	92232 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$146,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35Z R19	Rear Tyre Size:	255/35Z R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	56,710.50	34,804.80	21,905.70	38.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,064.00	10,684.00	11,380.00	51.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	78,774.50	45,488.80	33,285.70	42.25
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	77,974.50	44,688.80	33,285.70	42.69
+ GST 7.00/7.00% (S\$)	5,458.22	3,128.22	2,330.00	42.69
Nett Amount (S\$)	83,432.72	47,817.02	35,615.70	42.69

INSPECTION

Date of Assignment:	21/04/2022		
Date Inspected:	20/04/2022	Inspected At:	24 Benoi Sector Singapore 629857
Estimated Period of Repair:	12.0 days		Repairer: Premium Automobiles Pte Ltd

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Broken	2,493.00 FS	*1,800.80 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	425.00 FS	*- FS
3	1	*FRONT BUMPER SECURING STRIP	N/S Bent	79.00 FS	*31.60 FS
4	1	*FRONT BUMPER GRILLE -CENTER	Broken	219.00 FS	*174.80 FS
5	1	*FRONT BUMPER CLOSING ELEMENT -LOWER CENTER	Broken	254.00 FS	*203.20 FS
6	1	*FRONT BUMPER SPOILER	Not Necessary	599.00 FS	*- FS
7	2	*FRONT BUMPER AIR GUIDE -LH/RH	Broken	144.00 FS	*114.40 FS
8	1	*RADIATOR GRILLE	Broken	2,576.00 FS	*2,060.80 FS
9	2	*FRONT PARKING AID SENSOR SUPPORT -LH/RH	Cut	116.00 FS	*91.52 FS
10	1	*RADIATOR GRILLE COVER -UPPER	Broken	209.00 FS	*166.80 FS
11	1	*FRONT BUMPER AIR GUIDE GRILLE -LH/RH	N/S Cut	1,058.00 FS	*423.20 FS
12	1	*FRONT BUMPER FOAM FILLER PIECE	Broken	139.00 FS	*110.80 FS
13	1	*FRONT BUMPER REINFORCEMENT BEAM	Dented	899.00 FS	*719.20 FS
14	2	*FRONT BUMPER GUIDE SECTION -LH/RH	Not Necessary	82.00 FS	*- FS
15	2	*FRONT BUMPER BRACKET -LH/RH	Bent	508.00 FS	*406.40 FS
16	1	*FRONT BUMPER TOP COVER	Crushed	143.00 FS	*114.00 FS
17	1	*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
18	1	*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
19	1	*FRONT BUMPER LOCK CARRIAGE BRACKET	Broken	154.00 FS	*122.80 FS
20	2	*FRONT BUMPER SUPPORT -LH/RH	Necessary	64.00 FS	*51.04 FS
21	4	*POP RIVET	Necessary	4.00 FS	*2.88 FS
22	1	*FRONT PARKING AID SENSOR -INNER/OUTER (4PCS)	Broken (2pcs only)	1,060.00 FS	*390.24 FS
23	4	*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
24	1	*SET FRONT BUMPER WIRING	Not Necessary	567.00 FS	*- FS
25	2	*HORN -LH/RH	Not Necessary	273.00 FS	*- FS
26	2	*HORN SUPPORT-LH/RH	Not Necessary	66.00 FS	*- FS
27	1	*FRONT FENDER-LH/RH	N/S Dented	2,378.00 FS	*951.20 FS
28	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
29	1	*FRONT FENDER CLOSING ELEMENT -LH/RH	N/S Necessary	166.00 FS	*65.84 FS
30	1	*FRONT FENDER BRACKET-LH/RH	N/S Necessary	82.00 FS	*32.72 FS
31	10	*FRONT FENDER POP RIVET	Necessary	38.00 FS	*30.40 FS
32	1	*FRONT FENDER BRACE -LH/RH	N/S Bent	264.00 FS	*105.20 FS
33	2	*FRONT FENDER BRACKET CENTER -LH/RH	Not Necessary	79.00 FS	*- FS
34	2	*FRONT FENDER BRACKET CENTER LH/RH	Not Necessary	110.00 FS	*- FS
35	1	*FRONT FENDER TRIM -LH/RH	N/S Necessary	342.00 FS	*136.40 FS
36	1	*FRONT WHEEL HOUSING LINER -LH/RH	N/S Torn	598.00 FS	*238.80 FS
37	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	176.00 FS	*140.80 FS
38	2	*FRONT WHEEL SPOILER -LH/RH	Not Necessary	164.00 FS	*- FS
39	2	*FRONT WHEEL SPOILER LOWER-LH/RH	Not Necessary	79.00 FS	*- FS
40	1	*FRONT FENDER LEDGE COVER LONG -LH/RH (2PCS)	Broken (1pc only)	80.00 FS	*31.44 FS
41	1	*FRONT FENDER LEDGE COVER SHORT -LH/RH	N/S Broken	36.00 FS	*13.92 FS
42	1	*BONNET	Dented	3,491.00 FS	*2,792.80 FS
43	6	*BONNET CAP NUT	Not Necessary	27.00 FS	*- FS
44	1	*BONNET ATTACHMENT PARTS	Not Necessary	128.00 FS	*- FS
45	2	*BONNET HINGE LH/RH	Not Necessary	932.00 FS	*- FS
46	3	*BONNET IMPACT PROTECTION -LH/RH/CENTER	Necessary	93.00 FS	*73.20 FS
47	2	*BONNET STRIKER -LH/RH	Bent	112.00 FS	*89.12 FS
48	2	*BONNET LID LOCK	Bent	455.00 FS	*364.00 FS
49	1	*BONNET BOWDEN CABLE -CENTER	Not Necessary	64.00 FS	*- FS
50	1	*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
51	1	*BONNET BOWDEN CABLE -CENTER UPPER	Bent	64.00 FS	*50.56 FS
52	1	*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
53	2	*BONNET ABSORBER	Crushed	256.00 FS	*204.80 FS
54	1	*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
55	1	*BONNET PLENUM CHAMBER	Not Necessary	108.00 FS	*- FS
56	2	*HEADLIGHT -LH/RH	Broken	16,832.00 FS	*13,465.60 FS
57	2	*HEADLIGHT HOSE	Not Necessary	83.00 FS	*- FS
58	6	*SPACER	Not Necessary	270.00 FS	*- FS
59	2	*LIFT CYLINDER -LH/RH	Not Necessary	434.00 FS	*- FS
60	2	*LIFT CYLINDER BRACKET-LH/RH	Not Necessary	34.00 FS	*- FS
61	1	*LIFT CYLINDER CORUGATED PIPE	Crushed	100.00 FS	*79.44 FS
62	1	*LOCK CARRIER	Broken	1,127.00 FS	*901.60 FS
63	2	*LOCK CARRIER SUPPORT -LH/RH	Broken	85.00 FS	*67.68 FS
64	1	*A/C CONDENSER (NPA)	Dented	682.50 FS	*546.00 FS
65	1	*REFRIGERANT LINE	Bent	186.00 FS	*148.80 FS
66	1	*REFRIGERANT LINE	Bent	381.00 FS	*304.80 FS
67	1	*REFRIGERANT LINE	Bent	277.00 FS	*221.60 FS
68	1	*HIGH -PRESSURE VALVE	Not Necessary	52.00 FS	*- FS
69	1	*PRESSURE SENSOR	Not Necessary	206.00 FS	*- FS
70	1	*CHARGE AIR COOLER	Dented	654.00 FS	*522.80 FS
71	1	*CHARGE AIR COOLER PRESSURE HOSE	Not Necessary	413.00 FS	*- FS
72	1	*CHARGE AIR COOLER PRESSURE PIPE	Not Necessary	496.00 FS	*- FS
73	1	*RADIATOR	Dented	1,010.00 FS	*808.00 FS
74	6	*RADIATOR COOLANT	Necessary	282.00 FS	*225.60 FS
75	1	*RADIATOR FAN RING	Broken	291.00 FS	*232.40 FS
76	1	*RADIATOR FAN CONTROL UNIT	Dented	2,483.00 FS	*1,986.40 FS
77	2	*RADIATOR AIR GUIDE INNER -LH/RH	Broken	72.00 FS	*56.56 FS
78	2	*RADIATOR AIR GUIDE OUTER-LH/RH	Missing	38.00 FS	*29.28 FS
79	1	*RADIATOR AIR GUIDE -LOWER	Bent	25.00 FS	*19.68 FS
80	1	*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
81	1	*OUTSIDE TEMPERATURE SENSOR	Not Necessary	64.00 FS	*- FS
82	1	*INTAKE AIR DUCT -RH	Not Necessary	25.00 FS	*- FS
83	1	*INTAKE AIR GUIDE -TOP	Not Necessary	61.00 FS	*- FS
84	1	*INTAKE HOSE	Not Necessary	110.00 FS	*- FS
85	1	*AIR FILTER BOX	Not Necessary	418.00 FS	*- FS
86	2	*FRONT DOOR -LH/RH	Broken	342.00 FS	*272.80 FS
87	2	*ROOF MOLDING -LH/RH	Not Necessary	1,412.00 FS	*- FS
88	2	*FRONT DOOR WINDOW SLOT TRIM STRIP -LH/RH	Not Necessary	892.00 FS	*- FS
89	2	*FRONT WINDSCREEN DEFLECTOR STRIP -LH/RH	Not Necessary	150.00 FS	*- FS
90	1	*RADIATOR AIR GUIDE UPPER	Not Necessary	19.00 FS	*- FS
91	1	*NOISE INSULATION	Not Necessary	640.00 FS	*- FS
92	1	*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
93	1	*SUNDRIES	Necessary	500.00 FS	*251.28 FS
94	1	*BONNET SOUND ABSORBER (Supplimentary)	Crushed	382.00 FS	*305.60 FS
95	1	*REFRIGERANT PIPE (Supplimentary)	Bent	585.00 FS	*468.00 FS
96	1	*ENGINE OIL (Supplimentary)	Necessary	299.00 FS	*239.20 FS
97	1	*TIMING CASE (Supplimentary)	Dented	316.00 FS	*252.80 FS
98	2	*SILICONE SEALANT (Supplimentary)	Necessary	127.00 FS	*101.44 FS
99	1	*BELT TENSIONER DAMPER (Supplimentary)	Broken	162.00 FS	*129.20 FS
100	1	*VIBRATION DAMPER (Supplimentary)	Bent	301.00 FS	*240.40 FS
101	1	*FLAT CONTACT HOUSING (Supplimentary)	Broken	14.00 FS	*10.56 FS
102	1	*POLY-V-BELT (Supplimentary)	Torn	56.00 FS	*44.24 FS
103	1	*POTENTIAL DISTRIBUTOR (Supplimentary)	Shorted	590.00 FS	*472.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 56,710.50 34,804.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER ,CHARGE AIR COOLER AND RADIATOR .CHECK ELECTRICAL FANS AND CONTROL UNIT ,TO CARRY OUT PRESSURISE ,VACUUM AND REGAS	New	1,700.00	1,700.00
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM .TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR	New	560.00	560.00
5	TO DISMANTLE AND RENEW FRONT BUMPER ,BOTH FRONT FENDER ,BONNET AND BOTH HEADLIGHT .TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR .TO RENEW FRONT LOCK CARRIAGE AND ALIGN TO POSITION RE ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	8,000.00	3,000.00
6	TO RESPRAY FRONT BUMPER ,BONNET ,HINGES ,BOTH FRONT FENDERS ,BOTH FRONT DOORS AND BOTH UPPER A-PILLARS	New	8,000.00	2,750.00
7	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
9	TO RENEW LHS INNER AIR COND PIPE (Supplimentary)	New	280.00	280.00
10	TO REPAIR RHS FRONT CHASSIS FRAME COVER (Supplimentary)	New	800.00	250.00
11	TO DISMANTLE AND RENEW TIMING CASE AND OTHER ENGINE COMPONENTS. (Supplimentary)	New	780.00	780.00
Gross Labour Cost (\$\$)			22,064.00	10,684.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >