

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003691/ANCE2**Date:** 30/09/2022**REFERENCE**

Insured/Claimant:	MOHAMMAD RAWI BIN MARJUNI	Policy No:	1900249263-01
Date of Loss:	17/04/2022	Nature of Claim:	OD Claim No: 1000883243SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ5633Y		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK080345
Reg. Date:	25/11/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF48KA111627
Colour:	White	Odometer:	38498 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,105.00	4,939.60	16,165.40	76.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,242.00	6,977.00	12,265.00	63.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	40,347.00	11,916.60	28,430.40	70.46
+ GST 7.00/7.00% (S\$)	2,824.29	834.16	1,990.13	70.46
Nett Amount (S\$)	43,171.29	12,750.76	30,420.53	70.46

INSPECTION

Date of Assignment:	21/04/2022		
Date Inspected:	20/04/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	41.00 FS	*- FS
2	1		*FRONT FENDER -RH	Distorted	861.00 FS	*688.80 FS
3	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS
4	1		*FRONT FENDER END PLATE -RH	Damaged	81.00 FS	*64.24 FS
5	1		*FRONT FENDER BRACKET -RH	Damaged	41.00 FS	*32.72 FS
6	1		*FRONT FENDER BRACKET -CENTER RH	Damaged	55.00 FS	*44.00 FS
7	1		*FRONT FENDER POP RIVET (6 PCS)	Necessary	23.00 FS	*18.24 FS
8	1		*FRONT FENDER BRACE -RH	Not Necessary	132.00 FS	*- FS
9	1		*FRONT FENDER BRACKET END -RH	Not Necessary	36.00 FS	*- FS
10	1		*FRONT FENDER BRACKET -CENTER RH	Not Necessary	37.00 FS	*- FS
11	1		*FRONT FENDER BRACKET UPPER -RH	Not Necessary	37.00 FS	*- FS
12	1		*FRONT FENDER BRACKET COVER -RH	Not Necessary	13.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER -RH	Deformed	262.00 FS	*209.60 FS
14	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
15	1		*FRONT WHEEL SPOILER -RH	Not Necessary	82.00 FS	*- FS
16	1		*FRONT WHEEL SPOILER LOWER-RH	Not Necessary	40.00 FS	*- FS
17	1		*FRONT STONE CHIP GUARD -RH	Deformed	57.00 FS	*45.28 FS
18	1		*FRONT FENDER LEDGE COVER-LONG	Necessary	35.00 FS	*27.52 FS
19	1		*FRONT FENDER LEDGE COVER -SHORT	Necessary	26.00 FS	*20.16 FS
20	1		*A/B PILLAR -RH	Dented	2,874.00 FS	*2,299.20 FS
21	2		*RIVETTED CAP NUT	Not Necessary	12.00 FS	*- FS
22	1		*FRONT SILL TRIM STRIP RH	Necessary	133.00 FS	*106.00 FS
23	1		*DATA TAC	Necessary	515.00 FS	*412.00 FS
24	1		*FRONT DOOR -RH	Repair	3,431.00 FS	*- FS
25	1		*FRONT DOOR OUTER SEAL -RH	Not Necessary	229.00 FS	*- FS
26	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
27	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
28	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
29	1		*FRONT DOOR BUNGS	Not Necessary	5.00 FS	*- FS
30	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	1,153.00 FS	*- FS
31	1		*FRONT DOOR CATCH -RH	Not Necessary	116.00 FS	*- FS
32	1		*FRONT DOOR WINDOW GUIDE TRIM STRIP	Not Necessary	287.00 FS	*- FS
33	1		*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP -RH	Not Necessary	344.00 FS	*- FS
34	1		*ASSEMBLY CARRIER	Not Necessary	2,096.00 FS	*- FS
35	1		*WISHBONE LINK-RH	Not Necessary	605.00 FS	*- FS
36	1		*WISHBONE SUSPENSION GUIDE-RH	Not Necessary	1,057.00 FS	*- FS
37	1		*FRONT WISHBONE GUIDE-RH	Not Necessary	575.00 FS	*- FS
38	1		*FRONT WISHBONE GUIDE-RH	Not Necessary	575.00 FS	*- FS
39	1		*FRONT WHEEL BEARING HOUSING -RH	Not Necessary	1,070.00 FS	*- FS
40	1		*SWIVEL JOINT	Not Necessary	214.00 FS	*- FS
41	1		*FRONT WHEEL HUB	Not Necessary	498.00 FS	*- FS
42	1		*FRONT WHEEL BEARING DOUBLED FLANGE	Not Necessary	273.00 FS	*- FS
43	1		*SUSPENSION FORKS -RH	Not Necessary	293.00 FS	*- FS
44	2		*COUPLING ROD	Not Necessary	258.00 FS	*- FS
45	1		*GAS SHOCK ABSORBER	Not Necessary	332.00 FS	*- FS
46	1		*TRACK ROD	Not Necessary	109.00 FS	*- FS
47	1		*TIE ROD END	Not Necessary	217.00 FS	*- FS
48	1		*ARLIC SEALANT	Necessary	180.00 FS	*180.00 FS
49	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
50	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
51	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
52	1		*RHS FRONT TYRE (NPA)	Not Necessary	0.00 FS	*- FS
53	1		*RHS FRONT RIM (NPA)	Cut	0.00 FS	*- FS
54	1		*SUNDRIES	Necessary	500.00 FS	*31.12 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*WASH WATER RESERVIOR Supplemantary	Deformed	160.00 FS	*127.60 FS
56	1		*FRONT FENDER INNER BRACKET - RH Supplemantary	Damaged	42.00 FS	*33.12 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					21,105.00	4,939.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	350.00	280.00
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY ,BACK REST AB PILLAR TRIMS ,SILL TRIMS ,CARPETS ,ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	1,800.00
4	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL INSPECT FOR DAMAGES	New	3,200.00	0.00
5	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	0.00
6	TO DISMANTLE AND INSTALL FRONT BUMPER TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR ,TO CUT OUT AND WELD RHS A-PILLAR WITH RHS SILL PANEL .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	6,300.00	2,500.00
7	TO RESPRAY RHS FRONT FENDER RHS FRONT DOOR .RHS A-PILLAR RHS SILL PANEL AND DOOR ENTRANCE	New	4,000.00	1,925.00
8	TO RENEW RHS FRONT RIM WIRH TYRE ,TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			19,242.00	6,977.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >