



# ELITE ADJUSTMENTS (M) SDN. BHD.

(108135-H)

Licensed by Bank Negara Malaysia and Ministry of Home Affairs  
PRIVATE INVESTIGATORS, INSURANCE LOSS ADJUSTERS & SURVEYORS

Email: elitehq@easb.com.my

(調查、保險審估)

億例有限公司

Our ref. : TP/200810/02/17/JB/TCK

20 February 2017

**WONG CHIA HWEE**

NO 12 JALAN INDAH 28/12

TAMAN BUKIT INDAH 2

81200 JOHOR BAHRU

JOHOR DARUL TAKZIM

**WITHOUT PREJUDICE  
PRIVATE & CONFIDENTIAL**

Dear Sir / Madam,

**Re: Assessment Cost of Repair for Accident Vehicle**

Make : SUZUKI  
Model : SWIFT 1.5L A/T  
Year Model : 2009  
Regn No. : JLV 2636

Pursuant to your instruction, we have proceeded to inspect the condition of the above vehicle at M/S.  
KSK Automotive  
No 23 & 25 ,Jalan Enau 4  
Taman Teratai  
81300 Johor Bahru  
Johor D.T.

**Assessment Cost of Repairs**

Our recommended amount corresponds to Replacement parts, Labour charges, Towing and Spray painting.  
The breakdown of which is as follows: -

Replacement Parts	14,618.80
Labour Charges	1,750.00
Spray painting	1,250.00
Towing	-

---

<b>Total Repair Cost (RM)</b>	<b>17,618.80</b>
-------------------------------	------------------

---

**Extent of Damages**

Damage sustained to the REAR portions.

# Elite Adjustments (M) Sdn.Bhd.(108135-H)

60-A, Jalan 30A/119, Taman Taynton View, 56000 Cheras, Kuala Lumpur.

Tel : 03-91302111 / 91305111 Fax 03-91319111

Email : elitehq@easb.com.my / elitpax1@streamyx.com

## VEHICLE INSPECTION REPORT

OUR REF. : TP/200810/02/17/JB/TCK  
INSPECTION AT : KSK Automotive  
No 23 & 25 ,Jalan Enau 4  
Taman Teratai  
81300 Johor Bahru  
Johor D.T.

DATE OF INSPECTION 05 January 2017

THIRD PARTY REGN NO SJZ 4416 C

DATE OF LOSS 02 January 2017

INSURED : WONG CHIA HWEE

## IDENTIFICATION & DETAILS OF VEHICLE

REGN. NO. : JLV 2636  
MAKE : SUZUKI  
MODEL : SWIFT 1.5L A/T  
ENGINE NO. : M15A1387870  
CHASSIS NO. : PPPEZC21S00108096

YEAR : 2009  
COLOUR : METALLIC GREY  
SPEEDOMETER READING : 202211 Km/h  
CUBIC CAPACITY (C.C.) : 1490 c.c.  
CARRYING CAPACITY : 5

## ACCESSORIES

AIR-CONDITIONER : Yes  
WING MIRRORS : Yes  
RADIO : Yes  
SEAT BELTS : Yes  
3RD. BRAKE LIGHTS : Yes

## GENERAL CONDITION

PAINTWORK : Good  
HANDBRAKES : Good  
FOOT BRAKES : Good  
STEERING : Good  
ENGINE MODIFICATION : Nil

## TYRES PERCENTAGE OF REMAINING THREAD

7MM ===== 7MM

7MM ===== 7MM

Tyre : CONTINENTAL  
Size : 195/55/R15

## VEHICLE REPAIRABLE OR BORDERLINE

	Repairer's Estimates	Our Recom mendation
Replacement Parts	14,618.80	14,618.80
Labour	3,550.00	1,750.00
Spray Painting	2,550.00	1,250.00
Towing	-	-
Total Repair Cost	20,718.80	17,618.80
Different	3,100.00	

ESTIMATED PERIOD FOR REPAIR : app. 12 working days

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

No	Item	Description of Replacement Parts	JLV 2636	Condition	Repairer's Estimates	Our Recommendation	
1	1pc	Chassis Member Rear LH		Dented	843.60	x nn	843.60 Nett
2	1pc	Quarter Panel Inner LH		Dented	235.60	x nn	235.60 Nett
3	1pc	Quarter Panel Inner Upper LH		Dented	154.80	x nn	154.80 Nett
4	1pc	Quarter Panel LH		Dented	1,183.30	x R	1,183.30 Nett
5	1pc	Quarter Panel Liner Rear LH		Cut	297.80	180 -	297.80 Nett
6	1pc	Shock Absorber Rear		Bent	233.40	x nn	233.40 Nett
7	1pc	Suspension Spring Rear		Scratched	271.40	x nn	271.40 Nett
8	1pc	Wheel Rim Alloy		Scratched	1,385.00	x nn	1,385.00 Nett
9	1pc	Bumper Rear Cover		Torn	1,854.30	500 -	1,854.30 Nett
10	1pc	Bumper Rear Retainer / Guide LH		Cracked	54.80	-	54.80 Nett
11	2pcs	Bumper Rear Sensor @ RM183.80		Snapped	367.60	-	367.60 Nett
12	1pc	Bumper Rear Shock Absorber		Bent	81.90	x nn	81.90 Nett
13	1pc	Lamp Assembly Rear LH		Broken	535.40	-	535.40 Nett
14	1pc	Rear Panel		Dented	883.10	550 -	883.10 Nett
15	1pc	Tailgate		Dented	2,018.30	1200 -	2,018.30 Nett
16	1pc	Tailgate Aperture Weatherstrip		Cut	286.40	-	286.40 Nett
17	1pc	Tailgate Latch		Jammed	511.90	x nn	511.90 Nett
18	1pc	Tailgate Support Strut LH		Jammed	372.00	x nn	372.00 Nett
19	1pc	Tailgate Support Strut RH		Jammed	372.00	x nn	372.00 Nett
20	1pc	Tailgate Trimboard		Cracked	443.00	250 -	443.00 Nett
21	1pc	Boot Extractor Vent		Cut	115.20	-	115.20 Nett
22	1pc	Suspension Crossmember Rear		Bent	2,083.00	x nn	2,083.00 Nett
					14,583.80		14,583.80
23	1pc	Number Plate Rear	br		35.00		35.00 Nett
					14,618.80		14,618.80

- End of Part Descriptions -

Labour Charges -	JLV 2636	Replacement Parts B/F.....	14,618.80	14,618.80
------------------	----------	----------------------------	-----------	-----------

LABOUR

1	To remove and dismantle all damaged parts as listed above to facilitate repairs and replacement of parts. To weld and cut out to where necessary. To repair and knock out dents to where necessary. To refit, reweld new and repaired parts inclusive of adjusting same.	1,550.00	700	750.00
2	To disconnect wiring systems to effect other repairs, to reconnect same.	120.00	30	60.00
3	To check front and rear wheel alignment and tyres balancing.	120.00		60.00 X
4	To remove engine unit/gear box assy/exhaust system to facilitate repairs and replacement of parts and to refit same.	500.00		250.00 X
5	To hydraulic jack and realign front and rear LH & RH chassis frames and where necessary.	500.00		250.00 X
6	To supply labour to remove/refix rear windscreen glass to effect repairs and replacement of parts and to refit same	360.00	120	180.00
7	To supply rear windscreen glass sealants.	400.00	50	200.00

SPRAY PAINTING

8	To supply material for spray painting, underseal & antirust.	850.00	30	400.00
9	To supply labour for spray painting on the new and repaired parts and where necessary inclusive of cementing, polishing and underseal.	1,700.00	600	850.00

Total Labour :	6,100.00	3,000.00
Total Parts :	14,618.80	14,618.80
Total Repair C :	20,718.80	17,618.80
Different :	3,100.00	

- End of Labour charges -

7 days

Our ref. : TP/200810/02/17/JB/TCK  
Regn No.: JLV 2636

**Parts Prices**

Parts prices were obtained in nett basis at current quotation and are subject to change without prior notice.

**Remarks**

Nil.

**Consistency**

Based on the contents of the Police report lodged, the damages appears to be consistent.

**Note**

Please note that our above recommended figure is merely for you to hold it as a reference of settlement only. We shall not be held responsible for any other consequences which may arise on our above visual inspection of the said damaged vehicle.

**Enclosure**

Enclosed herewith a set of photographs of the said damaged vehicle and our bill for services rendered for your kind consideration.

Thanking you.

Yours faithfully,



ELITE ADJUSTMENTS (M) SDN.BHD.

Attended by: Tan Chee Ket