



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JLV 2636

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	CHASSIS MEMBER REAR LH	NOT NECESSARY	843.60	-
1	QUARTER PANEL INNER LH	NOT NECESSARY	235.60	-
1	QUARTER PANEL INNER UPPER LH	NOT NECESSARY	154.80	-
1	QUARTER PANEL LH	TO REPAIR SEE LABOUR	1,183.30	-
1	QUARTER PANEL LINER REAR LH	CUT	297.80	180.00
1	SHOCK ABSORBER REAR	NOT NECESSARY	233.40	-
1	SUSPENSION SPRING REAR	NOT NECESSARY	271.40	-
1	WHEEL RIM ALLOY	NOT NECESSARY	1,385.00	-
1	BUMPER REAR COVER	TORN	1,854.30	500.00
1	BUMPER REAR RETAINER / GUIDE LH	CRACKED	54.80	54.80
2	BUMPER REAR SENSOR @RM183.80	SNAPPED	367.60	367.60
1	BUMPER REAR SHOCK ABSORBER	NOT NECESSARY	81.90	-
1	LAMP ASSEMBLY REAR LH	BROKEN	535.40	535.40
1	REAR PANEL	DENTED	883.10	550.00
1	TAILGATE	DENTED	2,018.30	1,200.00
1	TAILGATE APERTURE WEATHERSTRIP	CUT	286.40	286.40
1	TAILGATE LATCH	NOT NECESSARY	511.90	-
1	TAILGATE SUPPORT STRUT LH	NOT NECESSARY	372.00	-
1	TAILGATE TRIMBOARD	CRACKED	443.00	250.00
1	BOOT EXTRACTOR VENT	CUT	115.20	115.20
1	SUSPENSION CROSSMEMBER REAR	NOT NECESSARY	2,083.00	-
1	TAILGATE SUPPORT STRUT RH	NOT NECESSARY	372.00	-
			14,583.80	4,039.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	NUMBER PLATE REAR (SN)	BROKEN	35.00	35.00
			35.00	35.00

Report Ref No. CS1/AWA22003698/Eqy3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE AND DISMANTLE ALL DAMAGED PARTS AS LISTED ABOVE TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS. TO WELD AND CUT OUT TO WHERE NECESSARY. TO REPAIR AND KNOCK OUT DENTS TO WHERE NECESSARY. TO REFIT, REWELD NEW AND REPAIRED PARTS INCLUSIVE OF ADJUSTING SAME. INCLUSIVE OF THE REPAIR OF QUARTER PANEL LH.		1,550.00	700.00
	TO DISCONNECT WIRING SYSTEMS TO EFFECT OTHER REPAIRS, TO RECONNECT SAME.		120.00	30.00
	TO CHECK FRONT AND REAR WHEEL ALIGNMENT AND TYRES BALANCING.	NOT NECESSARY	120.00	-
	TO REMOVE ENGINE UNIT / GEAR BOX ASSY / EXHAUST SYSTEM TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS AND TO REFIT SAME.	NOT NECESSARY	500.00	-
	TO HYDRAULIC JACK AND REALIGN FRONT AND REAR LH & RH CHASSIS FRAMES AND WHERE NECESSARY.	NOT NECESSARY	500.00	-
	TO SUPPLY LABOUR TO REMOVE / REFIX REAR WINDSCREEN GLASS TO EFFECT REPAIRS AND REPLACEMENT OF PARTS AND TO REFIT SAME.		360.00	120.00
	TO SUPPLY REAR WINDSCREEN GLASS SEALANTS.		400.00	50.00
	TO SUPPLY MATERIAL FOR SPRAY PAINTING, UNDERSEAL & ANTIRUST.		850.00	30.00
	TO SUPPLY LABOUR FOR SPRAY PAINTING ON THE NEW AND REPAIRED PARTS AND WHERE NECESSARY INCLUSIVE OF CEMENTING, POLISHING AND UNDERSEAL.		1,700.00	600.00
			6,100.00	1,530.00
	<b>GRAND TOTAL</b>		<b>20,718.80</b>	<b>5,604.40</b>
<b>RECOMMENDED COST OF REPAIRS (RINGGIT MALAYSIA)</b>				<b>5,604.40</b>

Report Ref No. CS1/AWA22003698/Eqy3e2

**CHEN TSUE YEE**

Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.