

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER :

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	
Policy No:		Date of Loss:	16/04/2022
Vehicle Reg. No.:	SJQ7748Y	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SMP8995M
Any Injuries?	yes	Contact No:	
Insured/Claimant:	SHAFUL AFIQ BIN MOHAMED SALLEH	Driver:	NUR NADIA BINTE KAMAL RUDIN

PARTS MODEL

Make/Model:	Hyundai, I30 1.6 - KMHDC51DM	Vehicle Reg. Date:	27/05/2009
Vehicle Colour:		Engine Number:	
Chassis No:	KMHDC51DR9U163241	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss Collision - Head to Rear
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	3,637.04
Miscellaneous Items	635.00
Labour	1,610.00
Paintwork Labour	1,310.00
Towing	0.00
Gross Total(\$\$):	7,192.04
GST 7.00%(\$\$):	503.44
Nett Amount(\$\$):	7,695.48

This claim is handled by: Sky Toh T C

Not Notified
U/Ring B
Presurvey After Repair
Kenneth (LKK) 4 days
96910663

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER	Bu 450.00	-20.00	360.00 ✓
2	1	REAR BUMPER SIDE RETAINER LH	Sm 80.00	-20.00	64.00 X
3	1	REAR BUMPER SIDE RETAINER RH	Sm 80.00	-20.00	64.00 X
4	1	REAR BUMPER INNER SPONGE	Sm 130.00	-20.00	104.00 X
5	1	REAR BUMPER REINFORCEMENT	280.00	-20.00	224.00 7
6	1	REAR TAILGATE	Ry 1,801.30	-20.00	1,441.04 ✓
7	1	REAR TAILGATE I30 EMBLEM	Me 55.00	-20.00	44.00 ✓
8	1	REAR TAILGATE RUBBER	Sm 85.00	-20.00	68.00 X
9	1	REAR TAILGATE LOCK	R 170.00	-20.00	136.00 X
10	1	REAR END PANEL	R 380.00	-20.00	304.00 X
11	1	REAR END PANEL INNER GARNISH	Sm 45.00	-20.00	36.00 X
12	1	REAR TAILLAMP LH	Sm 495.00	-20.00	396.00 X
13	1	REAR TAILLAMP RH	495.00	-20.00	396.00 7

Total Parts (S\$) 3,637.04

1845.00

1845.04

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR NUMBER PLATE	Sm 45.00	0.00	45.00 X
2	1	REAR BUMPER CLIPS (1 SET)	Me 40.00	0.00	40.00 ✓
3	1	REAR BUMPER SENSORS (1 SET)	Sm 250.00	0.00	250.00 200.00
4	1	REAR BUMPER CAMERA	Sm 200.00	0.00	200.00 X
5	1	REAR WINDSCREEN SEALANT	100.00	0.00	100.00 ✓

Sub Total (S\$) 635.00

340

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	50.00	0.00	50.00 150
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 500
3	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00 ✓
4	1	To Transfer Rear Tailgate.	80.00	0.00	80.00 600
5	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,300.00	0.00	1,300.00 4000

Gross Labour Cost (S\$) 1,640.00

625

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	50.00	0.00	50.00
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	0.00	60.00 } 300
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape	1,200.00	0.00	1,200.00 4000

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
-----	-----	-------------	--------	-------	------------

the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.

Gross Labour Cost (S\$) 1,310.00

430

< END OF ESTIMATES >

Parts = 1845.04
 Item = 340
 Labour = 625
 Paint = 430

= 3240.04
 - 20%

= \$2592.03

4/3 \$2600/-
 (p/s confirm)