



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 7000A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	DEFORMED	1,717.05	1,717.05
1	FRONT BUMPER SIDE RETAINER LH	DAMAGED	45.80	45.80
1	FRONT BUMPER PARKING SENSOR	MALFUNCTION	652.00	242.00
1	FRONT BUMPER NOZZLE COVER LH	MISSING	52.00	52.00
1	FRONT BUMPER FOG LAMP GARNISH LH	SERVICEABLE	155.00	-
1	FRONT BUMPER SIDE COVER LH	DAMAGED	102.30	102.30
1	FRONT BUMPER CENTRE BRACKET	BROKEN	199.00	199.00
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	216.50	-
1	HEADLAMP LH (ORIGINAL)	DEFACED	10,080.55	10,080.55
1	HEADLAMP NOZZLE LH	DAMAGED	266.00	266.00
1	FRONT FENDER LH	BENT / WARPED	901.95	901.95
1	FRONT SHOCK ABSORBER LH	SERVICEABLE	425.00	-
1	FRONT KNUCKLE ARM LH	SERVICEABLE	1,020.55	-
1	FRONT KNUCKLE ARM BEARING / HUB LH	SERVICEABLE	469.25	-
1	FRONT TIE ROD END LH	SERVICEABLE	245.50	-
1	FRONT LOWER CONTROL ARM LH	SERVICEABLE	829.60	-
1	FRONT RADIATOR GRILLE ASSY	SERVICEABLE	969.50	-
	LESS 5% DISCOUNT		-917.38	-
	LESS 10% DISCOUNT		-	-1,360.67
			17,430.17	12,245.98
<b>SPECIAL NETT ITEMS</b>				
1	FRONT TYRE RIM LH (SN)	DAMAGED	712.00	712.00
1	FRONT TYRE LH (SN)	SERVICEABLE	250.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	20.00
			1,012.00	732.00
<b>LABOUR</b>				
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS.		855.00	400.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		600.00	500.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		20.00	20.00
	SPECIALIST CHARGES - WHEEL ALIGNMENT.		80.00	60.00
	SPECIALIST CHARGES - CHECK / DIAGNOSTIC AND REPROGRAMMING.		150.00	50.00
	REMOVE AND REPLACE FRONT UNDERCARRIAGE WORK LH.	NOT NECESSARY	225.00	-
	REMOVE AND REPLACE FRONT PARKING SENSOR.		90.00	40.00
	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY)		36.00	30.00
			2,056.00	1,100.00
	<b>GRAND TOTAL</b>		<b>20,498.17</b>	<b>14,077.98</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>11,250.00</b>

Report Ref No. CS3/INC21012107/Gvy3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**