

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22003702/UPA3Q2
Date: 28/10/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100395976-07
Claimant Vehicle No :	SJZ204Z	Insured Vehicle No :	SKQ6794H
Date of Loss:	21/04/2022	Nature of Claim:	TP
		Claim No:	1529953024SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ204Z		
Make & Model:	TOYOTA ALPHARD, 2.5 CVT ELEGANCE S/R (A)	Engine No:	2ARH518073
Reg. Date:	22/06/2015 (Man. Year: 2015)	Chassis No:	JTNGF3DH808000212
Colour:	White	Odometer:	204066 km
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,062.20	5,694.42	12,367.78	68.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,810.00	1,520.00	45.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,392.20	7,504.42	13,887.78	64.92
Approved Total (Overridden) (\$\$)		6,000.00		
(\$\$)	21,392.20	6,000.00	15,392.20	71.95
+ GST 7.00/7.00% (\$\$)	1,497.45	420.00	1,077.45	71.95
Nett Amount (\$\$)	22,889.65	6,420.00	16,469.65	71.95
+ Car Rental (4.0 x S\$180.00/day) (\$\$)		720.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		7,142.00		
Global Sum Settlement (\$\$)		7,000.00		

INSPECTION

Date of Assignment:	21/04/2022		Fastech Auto Pte Ltd (HQ)
Date Inspected:	21/04/2022	Inspected At:	1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Estimated Period of Repair:	4.0 days		Singapore 417883

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,866.10 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Not Necessary	199.50 F	*- FL
3	1		*TAILGATE	Badly Dented	2,650.20 F	*2,164.40 FL
4	1		*TAILGATE ALPHARD EMBLEM	Necessary	105.10 F	*105.10 FL
5	1		*TAILGATE WEATHERSTRIP	Not Necessary	388.90 F	*- FL
6	1		*TAILGATE INNER LOCK	Damaged / Shorted	650.20 F	*650.20 FL
7	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	955.80 F	*736.60 FL
8	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
9	1		*TAILGATE REFLECTORS	N/S Not Necessary / O/SCracked	1,378.20 F	*689.10 FL
10	1		*TAILGATE OUTER GARNISH	Not Necessary	855.20 F	*- FL
11	1		*REAR BUMPER	Dented / Deformed	1,850.00 F	*1,650.00 FL
12	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	170.00 F	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*REAR BUMPER TOW COVER	Not Necessary	48.00 F	*- FL
15	1		*REAR BUMPER PDC SENSORS	O/S Shorted	530.00 F	*265.00 FL
16	2		*REAR BUMPER REFLECTORS	Not Necessary	196.00 F	*- FL
17	1		*REAR END PANEL	Repair	911.20 F	*- FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	245.20 F	*- FL
19	2		*TAILLAMPS	Not Necessary	1,900.20 F	*- FL
20	2		*TAILLAMP LOWER GARNISHS	Not Necessary	1,300.20 F	*- FL
21	1		*REAR ANTENNA SENSOR	Not Necessary	226.20 F	*- FL
22	1		*REAR BUZZER SENSOR	Not Necessary	210.50 F	*- FL
23	1		*REAR BALANCING RETAINER BAR	Damaged / Bent	1,125.50 F	*1,125.50 FL
24	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
25	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
26	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
27	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,062.20	7,565.90
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,871.48
Total Parts (\$)	18,062.20	5,694.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX TAILGATE MECHANISM	New	100.00	80.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	100.00
6	TO SPRAY RUST PROOFING	New	100.00	40.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (S\$)			3,330.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >