

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22003703/VQY3N2**Date:** 27/05/2022**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MU001138
Claimant Vehicle No :	SHC8466B	Insured Vehicle No :	SJF8881X
Date of Loss:	20/04/2022	Nature of Claim:	TP
		Claim No:	M2201883

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8466B	Engine No:	2ZR2H91944
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU703093743
Reg. Date:	24/03/2022 (Man. Year: 2020)	Odometer:	7364 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,189.04	1,864.05	324.99	14.85
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,150.00	940.00	210.00	18.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,350.04	2,815.05	534.99	15.97
+ GST 7.00/7.00% (S\$)	234.50	197.05	37.45	15.97
Nett Amount (S\$)	3,584.54	3,012.10	572.44	15.97

INSPECTION

Date of Assignment:	21/04/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	21/04/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$2,815.04

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 May 2022)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC8466B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER ASSY	Dented	503.04 FL	-	*503.04 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*REAR BUMPER CENTRE GUIDE	Scratched	654.96 FL	-	*654.96 FL
4	1		*REAR BUMPER TOW COVER	Scratched	82.70 FL	-	*82.70 FL
5	1		*REAR BUMPER REFLECTOR RH	Serviceable	55.00 FL	-	*- FL
6	1		*REAR BUMPER BEAM	Serviceable	378.32 FL	-	*- FL
7	1		*REAR BUMPER BRACKET RH	Necessary	94.80 FL	-	*94.80 FL
8	1		*TAILLAMP ASSY UPPER RH	Cracked	557.90 FL	-	*557.90 FL
9	1		*TAILLAMP ASSY LOWER RH	Cracked	570.00 FL	-	*570.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,918.72	2,485.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	729.68	621.35
Total Parts (\$\$)	2,189.04	1,864.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	600.00	500.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	30.00
5	REMOVE/REFIX REVER SENSOR	New	50.00	30.00
Gross Labour Cost (\$\$)			1,150.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >