





CONFIRMATION / ESTIMATE COST OF REPAIRS

861 6758 Ruidi	MODEL: FORESTER 2.01-L AWD CVT YEAR: 27 APRIL 2018
ENGINE NO: FB20YD31742	CHASSIS NO: JF1SJ5KC5JG107630
DATE IN:	CASH REPAIR ESTIMATE / QUOTATION

S/N	NATURE OF JOB			AMOUNT	
1.	TO RESPRAY WHOLE CAR			\$3700	
2.	TO INSTALL ALL MOULDINGS AND NECESSARY ITEM	S		\$1000 800	
S/N	Total Labour				
S/N	PARTS DESCRIPTION		PRIC	E	
1.		QTY	LIST	S/NETT	
2.	FRONT BUMPER / (Stalm? by Palm)	1	\$610.50		
3.	FRONT SPORT GRILLE	1	\$600		
4.	FRONT BUMPER UNDER SPOILER / "	1	\$699		
5.	LAMP ASSEMBLY HEADLIGHT - RIGHT /	1	\$2380		
6.	LAMP ASSEMBLY HEADLIGHT – LEFT / "	1	\$2380		
7.	DAM RUBBER-FRONT LOWER / APK	1	\$14.80		
8.	DAM RUBBER-FRONT UPPER - PC	1	\$14.80		
9.	FRONT WINDOW MOULDING / ML	1	\$111.00		
10.	WEATHER STRIP-DOOR OUT RIGHT X	1	\$103.60		
11.	WEATHER STRIP-DOOR OUT RIGHT	1	\$103.60		
12.	TAPE FRONT DOOR SASH RIGHT / "	1	\$18.50		
13.	TAPE FRONT DOOR SASH LEFT / "	1	\$18.50		
14.	TAPE REAR DOOR SASH RIGHT / "	1	\$18.50		
15.	TAPE REAR DOOR SASH RIGHT / "	1	\$18.50		
16.	TAPE FRONT DOOR SASH REAR RIGHT /	i	\$18.50		
17.	TAPE FRONT DOOR SASH REAR LEFT / "	i	\$18.50	_	
18.	TAPE REAR DOOR SASH CENTRE RIGHT	1	\$11.10		
19.	TAPE REAR DOOR SASH CENTRE LEFT	1	\$11.10	+	
20.	TAPE REAR DOOR SASH REAR RIGHT	1	\$14.80	-	
21.	TAPE REAR DOOR SASH REAR LEFT	1	\$14.80	-	
22.	TAPE FRONT DOOR RIGHT	1	\$5.60	-	
23.	TAPE FRONT DOOR LEFT	i	\$5.60	-	
24.	RUN CHANNEL FRONT DOOR RIGHT	i	\$74.00	+	
25.	RUN CHANNEL FRONT DOOR LEFT / II	1	\$74.00		
26.	RUN CHANNEL REAR DOOR RIGHT /	1	\$74.00		
27.	RUN CHANNEL REAR DOOR LEFT /	1	\$74.00		
28.	WEATHER STRIP DOOR REAR OUTER RIGHT	1	\$103.60	+	
	WEATHER STRIP DOOR REAR OUTER LEFT / "	1	\$103.60	-	
29.	RUBBER REAR GATE	1	\$13.00	-	
30.	DAM RUBBER REAR GATE GLASS / NCC	1 2	\$7.40	-	
31.	A CONTRACTOR OF THE PROPERTY O	1	\$59.20	-	
32.	MUD GUARD REAR LEFT &		\$59.20	-	
33.		- 1			
34.	REAR BUMPER UNDER SPOILER /	11	\$851.00		

1	35.	LENS & BODY DE LE SELECTION LAND BIGHT	1	\$444.00	
SIABOD STAR COMBINATION LAW East SIAB.00	36.	LENS & BODY REAR COMBINATION LAMP RIGHT	i		
1 \$22.20	37	LENS & BODY REAR COMBINATION LAMP LETT	1	\$148.00	
PROTECTOR REAR GARNISH	38.	PROTECTOR REAR GATE X	1	\$22.20	
1	39.	THE TECTOR REAR GARNISH	2	\$11.20	
1	40.	THOTECTOR REAR GARNISH	1	\$81.40	
1 \$66.60	41.		i	\$40.70	
3. LETTER MARK R SPORT	42.	LETTER MARK REAR (NO-STOCK)	i	\$66.60	
4. ARM ASSEMBLY WINDSHIELD WIPER DRIVER / 1	43.		i	\$74.00	
Solution	44.		1	\$61.20	
6. BLADE ASSEMBLY WINDSHIELD WIPER ASSISTOR	45.	AUGU ASSEMBLY WINDSHIELD WIFER DRIVER >	i	\$61.20	
7. BLADE ASSEMBLY WINDSHIELD WIPER DRIVER 2 8. ARM ASSEMBLY REAR WIPER	46.	THE ASSEMBLY WINDSHIELD WIFER ASSISTER	i		
8. ARM ASSEMBLY REAR WIPER	The state of the s	BEADE ASSEMBLY WINDSHIELD WIPER DRIVER	1	\$48.10	
9. BLADE ASSEMBLY REAR WIPER	48.		1	\$44.40	
0. ROOF RAIL ASSEMBLY RIGHT / 1 \$444.00 1. ROOF RAIL ASSEMBLY LEFT // 1 \$444.00 2. MOULDING ROOF RIGHT / // 1 \$74.00 3. MOULDING ROOF LEFT // 1 \$230.00 4. REAR BUMPER CARGO STEP PANEL S/S / / 1 \$230.00 SUB TOTAL:	49.		i	\$25.90	
1. ROOF RAIL ASSEMBLY LEFT	50.		i	\$444.00	
2. MOULDING ROOF RIGHT	51.		i	\$444.00	
3. MOULDING ROOF LEFT	52.	ROOF INTIL ASSEMBLT LEFT	1	\$74.00	
4. REAR BUMPER CARGO STEP PANEL S/S / 1 \$230.00 SUB TOTAL:	53.		1	\$74.00	
SUB TOTAL:	54.	MODED ING ROOF EEFT	1	\$230.00	
PARTS TOTAL \$11563.90 TOTAL \$16263.90 GST 7% \$1138.48			OTAL:	- 79	0/
PARTS TOTAL \$11563.90 TOTAL \$16263.90 GST 7% \$1138.48	-			- 1-	10
PARTS TOTAL \$11563.90 TOTAL \$16263.90 GST 7% \$1138.48		LADOUR	ГОТАІ		\$4700
TOTAL \$16263.90 GST 7% \$1138.48					
GST 7% S1138.48			The second second		
517402.2					CAMPAGE STREET, STREET
GRAND TOTAL 317402.5					
		GRAND T	OTAL		317402.30

DATE APPROVAL:	
TIME APPROVAL:	
CONTACT PERSON:	MUHAMAMD RUSYDI
DID / EMAIL / HP:	86116758 - MUHAMMADRUSYDI@MOTORIMAGE.NET

REPAIR DAYS REQUIRED: 15-16 WORKING DAYS

** Please also be informed that the attached is an estimate based on our physical inspection and does not cover any additional parts or labour which may be required after the work has been opened up. Occasionally after the work has started, damaged or broken parts are discovered which are not evident on the first inspection. **

Stove CLKK) 6/5/22, 2.39pc 8322 8813

00-MK EXC. -? P/P MM MM 15 ds

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after soray panding
- . To display damaged partis) duting reservey
- Parts prices are subject to card and to card and
- Third party survey is on a "Without Project in
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer