

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22003708/KQY3Q2**Date:** 26/05/2022**REFERENCE**

Insured/Claimant: SG CAR CHOICES 2 PTE LTD

Policy No: DMHCSNW00007662100

Date of Loss: 19/04/2022

Nature of Claim: OD

Claim No: SNM22D202670/C01/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMZ9927B**

Make &amp; Model: TOYOTA CAMRY, 2.5 HYBRID ASCENT (A)

Engine No: A25A0A23860

Reg. Date: 28/05/2021 (Man. Year: 2020)

Chassis No: JTNB23HK703074357

Colour: Metallic Red

Odometer: 75990 km

Engine Capacity: 2487 cc

Market Value/New Car Price: S\$153,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/55R17

Rear Tyre Size: 215/55R17

Front Left Side: Michelin 2 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 2 mm

Rear Right Side: Michelin 4 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,406.00	6,167.00	2,239.00	26.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	432.60	243.60	189.00	43.69
Paintwork Labour	372.37	332.81	39.56	10.62
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,210.97</b>	<b>6,743.41</b>	<b>2,467.56</b>	<b>26.79</b>
<b>- Excess (S\$)</b>	0.00	2,000.00	-2,000.00	
<b>(S\$)</b>	9,210.97	4,743.41	4,467.56	48.50
<b>+ GST 7.00/7.00% (S\$)</b>	644.77	332.04	312.73	48.50
<b>Nett Amount (S\$)</b>	<b>9,855.74</b>	<b>5,075.45</b>	<b>4,780.29</b>	<b>48.50</b>

**INSPECTION**

Date of Assignment: 21/04/2022 Present Location:

Ding Auto Pte Ltd (HQ)

Date Inspected: 22/04/2022 Inspected At:

Ding Auto Pte Ltd (HQ)

176 Sin Ming Drive #04-06, Sin Ming Autocare  
Singapore 575721

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 26 May 2022)

**Parts:** 143      TOYOTA CAMRY 2.5 HYBRID ASCENT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMZ9927B)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*TOTAL PARTS</b>		8,193.00 F	*5,954.00 F
<b><u>Supplementary #1</u></b>						
2	1		<b>*TOWING HOOK COVER</b>	Dented	25.00 F	*25.00 F
3	1		<b>*LOW PITCHED HORN</b>	Dented	60.00 F	*60.00 F
4	1		<b>*L/RADIATOR AIR GUIDE</b>	Cracked	35.00 F	*35.00 F
5	1		<b>*RADIATOR UPPER MOUNTING BRACKET</b>	Distorted	42.00 F	*42.00 F
6	1		<b>*AIR COND O-RING SEAL</b>	Necessary	23.00 F	*23.00 F
7	1		<b>*COVER CLIP-PIN HOLD</b>	Necessary	12.00 F	*12.00 F
8	1		<b>*FENDER RETAINER CLIP</b>	Necessary	16.00 F	*16.00 F
					<b>Total Parts (\$\$)</b>	<b>8,406.00      6,167.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	Total Paint Labour	New	235.20	197.40
2	Total Paint Materials	New	137.17	135.41
<b>Labour Items</b>				
3	Total Panel/Mechanical Labour	New	432.60	243.60
<b>Gross Labour Cost (\$\$)</b>			<b>804.97</b>	<b>576.41</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >