

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation	n Internationale Des	Experts En Automobile
--------------------------	----------------------	-----------------------

CHINA TAIPING INSURANCE (S) PTE LTD

C/O TOPLIS AND HARDING (S) PTE LTD

133 CECIL STREET #17-01A KECK SENG TOWER SINGAPORE 069535 Ref: CS/TPS22003710/Eqy3e2

Date: 19/08/2022

	SINGAI OILE 009	300	Code:	СТІ			
1.	Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKV 8325P			
	Policy No.	Y226205	Coverage (\$)	0.00			
	Claim No.	SNC22D200008	Excess (\$)	0.00			
	Assign From	VICTOR FONG	Assign Date	21/04/2022			
2.	2. Vehicle Particulars & Condition						
	Make & Model	B.M.W. 216I	c.c	1499			
	Engine No.	HIDDEN	Year of Reg.	2018			
	Chassis No.	WBA2X92090VD11354	Colour	SILVER			
	Odometer	35942 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3.	. Conditions of Tyres						
		Size	Make	Balance			
	R/H Front Tyre	205/55 R17	BRIDGESTONE	4 mm			
	L/H Front Tyre	205/55 R17	BRIDGESTONE	4 mm			
	R/H Rear Tyre	205/55 R17	BRIDGESTONE	4 mm			
	L/H Rear Tyre	205/55 R17	BRIDGESTONE	4 mm			
4.	Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE WHOLE VEHICLE. THE CAUSE OF DAMAGE DUE TO AFFECTED BY FINE SPRAY PAINTING DROPLETS.						
	DAMAGES SEE DETAILS.						
5.	General Information						
	Accident Date	21/03/2022	Inspection Date	27/04/2022			
	Survey held at	PERFORMANCE MOTORS LTD					
		303 ALEXANDRA ROAD SINGAPORE 159941					
5a.	Remarks						
	A)THE INSPECTION B)IN ACCORDANCE	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 29 Working Days						