

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003711/TVY3E2**Date:** 05/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00013262200
Claimant Vehicle No :	SJN1848Y	Insured Vehicle No :	GBC820K
Date of Loss:	19/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202677/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN1848Y	Engine No:	1NZR745910
Make & Model:	TOYOTA SIENTA HYBRID, 1.5 G (A)	Chassis No:	NHP1707158004
Reg. Date:	25/07/2019 (Man. Year: 2019)	Odometer:	77364 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,574.12	4,457.50	7,116.62	61.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,020.00	1,770.00	3,250.00	64.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,594.12	6,227.50	10,366.62	62.47
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	16,594.12	5,000.00	11,594.12	69.87

INSPECTION

Date of Assignment:	21/04/2022	
Date Inspected:	22/04/2022	Inspected At: 8 Kaki Bukit Avenue 4 #01-49 Premier @ Kaki Bukit
Estimated Period of Repair:	6.0 days	Repairer: JEW Motors (HQ)

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2023)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN1848Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	642.00 FL	*642.00 FL
2	1		*REAR BUMPER UPPER CENTRE	Deformed	195.20 FL	*195.20 FL
3	1		*REAR BUMPER REFLECTOR RH	Not Necessary	58.60 FL	*- FL
4	1		*REAR BUMPER REFLECTOR LH	Cut	58.60 FL	*58.60 FL
5	1		*REAR BUMPER REFLECTOR GARNISH RH	Not Necessary	128.70 FL	*- FL
6	1		*REAR BUMPER REFLECTOR GARNISH LH	Cut	128.70 FL	*128.70 FL
7	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	69.80 FL	*- FL
8	1		*REAR BUMPER SIDE RETAINER LH	Cracked	69.80 FL	*69.80 FL
9	1		*REAR BUMPER TOW HOOK COVER	Deformed	24.70 FL	*24.70 FL
10	2		*REAR BUMPER REVERSE SENSOR	Not Working	344.80 FL	*200.00 FL
11	1		*REAR TAILLAMP ASSEMBLY RH	Not Necessary	520.70 FL	*- FL
12	1		*REAR TAILLAMP ASSEMBLY LH	Cracked	520.70 FL	*450.00 FL
13	1		*REAR TAILLAMP LOWER BRACKET RH	Not Necessary	45.60 FL	*- FL
14	1		*REAR TAILLAMP LOWER BRACKET LH	Cracked	45.60 FL	*45.60 FL
15	1		*REAR TAILGATE	Bent	1,142.50 FL	*1,142.50 FL
16	1		*REAR TAILGATE REFLECTOR LAMP RH	Not Necessary	520.70 FL	*- FL
17	1		*REAR TAILGATE REFLECTOR LAMP LH	Cracked	520.70 FL	*281.00 FL
18	1		*REAR TAILGATE OUTER GARNISH	Cracked	243.70 FL	*243.70 FL
19	1		*REAR TAILGATE INNER HANDLE	Not Necessary	76.40 FL	*- FL
20	1		*REAR TAILGATE EMBLEM	Necessary	68.20 FL	*68.20 FL
21	1		*REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	Necessary	52.50 FL	*52.50 FL
22	1		*REAR TAILGATE LOCK ASSEMBLY	Not Necessary	472.40 FL	*- FL
23	1		*REAR TAILGATE LOCK CATCH	Not Necessary	38.90 FL	*- FL
24	1		*REAR TAILGATE HINGE RH	Not Necessary	61.20 FL	*- FL
25	1		*REAR TAILGATE HINGE LH	Not Necessary	61.20 FL	*- FL
26	1		*REAR TAILGATE DAMPER RH	Not Necessary	229.70 FL	*- FL
27	1		*REAR TAILGATE DAMPER LH	Not Necessary	229.70 FL	*- FL
28	1		*REAR TAILGATE INNER TRIM	Not Necessary	578.60 FL	*- FL
29	2		*REAR TAILGATE STOPPER	Not Necessary	49.20 FL	*- FL
30	1		*REAR TAILGATE WEATHERSTRIP	Cut	376.00 FL	*376.00 FL
31	1		*REAR TAILGATE DETECTOR	Not Necessary	239.10 FL	*- FL
32	1		*REAR TAILGATE DETECTOR WIRE HARNESS	Not Necessary	288.90 FL	*- FL
33	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Necessary	97.80 FL	*97.80 FL
34	1		*REAR END PANEL (OUTER)	Bent	438.20 FL	*438.20 FL
35	1		*REAR END PANEL (INNER)	Repair	702.90 FL	*- FL
36	1		*REAR END PANEL TOP GARNISH	Deformed	145.20 FL	*145.20 FL
37	1		*REAR STORAGE BOX	Deformed	123.20 FL	*123.20 FL
38	1		*REAR STORAGE BOX COVER BOARD	Not Necessary	475.10 FL	*- FL
39	1		*REAR FLOOR PANEL	Not Necessary	698.20 FL	*- FL
40	1		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	627.10 FL	*- FL
41	1		*REAR FENDER INNER TRIM BOARD LH	Deformed	627.10 FL	*627.10 FL
42	1		*REAR FENDER INNER COWLING RH	Not Necessary	129.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR FENDER INNER COWLING LH	Not Necessary	129.10 FL	*- FL
44	1		*REAR EXHAUST PIPE	Not Necessary	925.40 FL	*- FL
45	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	64.00 FL	*- FL
46	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
47	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
48	1		*SET REAR TAILLAMP ASSEMBLY CLIPS	Necessary	50.00 FS	*10.00 FS
49	1		*SET REAR TAILGATE REFLECTOR LAMP CLIPS	Not Necessary	50.00 FS	*- FS
50	1		*SET REAR TAILGATE INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
51	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
52	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
53	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
54	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	40.00 FS	*- FS
55	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	120.00 FS	*50.00 FS
56	1		*REAR TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
57	1		*REAR END PANEL OUTER SEALANT	Necessary	120.00 FS	*40.00 FS
58	1		*REAR END PANEL INNER SEALANT	Not Necessary	120.00 FS	*- FS
59	1		*REAR FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS
60	1		*REAR TAILGATE REVERSE CAMERA	Cracked	500.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,895.50	5,810.00
- List Item Discount on L Items 25.00/25.00% (\$)	3,321.38	1,352.50
Total Parts (\$)	11,574.12	4,457.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE & REFIX PARTS	New	1,800.00	700.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,600.00	700.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO TRANSFER REAR TAILGATE MECHANISM	New	150.00	60.00
5	TO REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS	New	150.00	120.00
6	TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	120.00	30.00
7	TO REMOVE & REFIX REAR TAILGATE REVERSE CAMERA	New	150.00	30.00
8	TO REMOVE & REFIX REAR EXHAUST PIPE	New	120.00	0.00
9	TO APPLY ANTI RUST ON AFFECTED PARTS	New	100.00	40.00
10	TO REMOVE & REFIX INTERIOR UPHOLSTRY TO FACILITATE REPAIRS	New	150.00	60.00
11	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
12	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT .PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (S\$)			5,020.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >