

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3526P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER SIDE BRACKET RH	SERVICEABLE	55.80	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
1	REAR BUMPER CENTRE MOULDING	SERVICEABLE	451.25	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-276.65	-4.40
			1,106.60	17.60
	NETT ITEMS			
1	REAR NUMBER PLATE W/HOLDER (N)	CRACKED	55.00	55.00
1	REAR REVERSE SENSOR (N)	CUT	180.00	180.00
	LESS 10% DISCOUNT		-23.50	-23.50
			211.50	211.50
	SPECIAL NETT ITEMS			
2	REAR BUMPER ADVERTISEMENT LH/RH (SN)	NECESSARY	200.00	200.00
			200.00	200.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		450.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	20.00
			810.00	620.00
	GRAND TOTAL		2,328.10	1,049.10





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		850.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22003714/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser