

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22003718/APA3Q2**Date:** 13/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000102
<b>Claimant Vehicle No :</b>	SDV5336K	<b>Insured Vehicle No :</b>	SMR9046K
Date of Loss:	09/04/2022	Nature of Claim:	TP
		Claim No:	0563311626SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SDV5336K</b>	Engine No:	3ZRB734514
Make & Model:	TOYOTA HARRIER, 2.0 Elegance (A)	Chassis No:	ZSU600073099
Reg. Date:	08/04/2016 (Man. Year: 2015)	Odometer:	65160 km
Colour:	Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,400.00	1,400.00	1,000.00	41.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	530.00	920.00	63.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,850.00</b>	<b>1,930.00</b>	<b>1,920.00</b>	<b>49.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,850.00</b>	<b>1,500.00</b>	<b>2,350.00</b>	<b>61.04</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment:	20/04/2022	
Date Inspected:	20/04/2022 Inspected At:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Distorted	1,400.00 FS	*1,400.00 FS
2	1		*FRT BUMPER GRILLE	Not Necessary	350.00 FS	*- FS
3	1		*FRT GRILLE	Not Necessary	650.00 FS	*- FS
					<b>Total Parts (\$\$)</b>	<b>2,400.00 1,400.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING /WELDING WORKS	New	600.00	250.00
2	TO SPRAY PAINTING	New	800.00	250.00
3	TO CHECK WIRING	New	50.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,450.00</b>	<b>530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >