

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22003725/AQY3N2**Date:** 25/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00058022200		
<b>Claimant Vehicle No :</b>	GBK4426Y	<b>Insured Vehicle No :</b>	SJX2229A		
Date of Loss:	15/04/2022	Nature of Claim:	TP	Claim No:	SNM22D202585/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBK4426Y</b>		
Make & Model:	NISSAN NV200, 1.6 VANETTE DX (A)	Engine No:	HR16169257D
Reg. Date:	29/07/2020 (Man. Year: 2020)	Chassis No:	VM20157135
Colour:	Silver	Odometer:	40706 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	165/80R14	Rear Tyre Size:	165/80R14
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,351.45	2,554.75	1,796.70	41.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,340.00	1,290.00	49.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,981.45</b>	<b>3,894.75</b>	<b>3,086.70</b>	<b>44.21</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,100.00</b>		
<b>(\$\$)</b>	6,981.45	3,100.00	3,881.45	55.60
<b>+ GST 7.00/7.00% (\$\$)</b>	488.70	217.00	271.70	55.60
<b>Nett Amount (\$\$)</b>	<b>7,470.15</b>	<b>3,317.00</b>	<b>4,153.15</b>	<b>55.60</b>

**INSPECTION**

Date of Assignment:	22/04/2022	
Date Inspected:	25/04/2022 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 25 May 2022)	
<b>Parts:</b>	N/A	NISSAN NV200 1.6 VANETTE DX (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBK4426Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	485.90 FL	*485.90 FL
2	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	74.40 FL	*- FL
3	1		*REAR RH ARCH PANEL	Repair	1,353.60 FL	*- FL
4	1		*REAR RH TAILLAMP	Cut	258.00 FL	*258.00 FL
5	1		*REAR RH WHEEL BEARING HUB	Damaged	346.60 FL	*346.60 FL
6	1		*REAR SLIDING DOOR	Dented	1,229.00 FL	*1,229.00 FL
7	1		*REAR SLIDING DOOR INNER PLASTIC SEAL COVER	Not Necessary	35.00 FL	*- FL
8	1		*REAR BUMPER CLIPS - SET	Necessary	50.00 FS	*30.00 FS
9	1		*REAR RH TAILLAMP CLIPS - SET	Necessary	30.00 FS	*10.00 FS
10	1		*REAR RH TYRE	Not Necessary	250.00 FS	*- FS
11	1		*REAR RH WHEEL RIM	Cut	207.20 FS	*207.20 FS
12	1		*REAR SLIDING DOOR 3D ART WORK STICKER	Necessary	280.00 FS	*180.00 FS
13	1		*REAR SLIDING DOOR GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
14	1		*REAR SLIDING DOOR INNER TRIM BOARD CLIPS - SET	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,729.70</b>	<b>2,786.70</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	378.25	231.95
<b>Total Parts (\$\$)</b>	<b>4,351.45</b>	<b>2,554.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.	New	60.00	60.00
2	TO REMOVE, REINSTALL WINDOW GLASS. (TO FR)	New	120.00	0.00
3	TO REMOVE, REINSTALL REAR SUSPENSION AND UNDERCARRIAGE PART. (TO FR)	New	150.00	80.00
4	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.	New	100.00	80.00
5	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	120.00	0.00
6	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE.	New	100.00	60.00
7	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	New	1,000.00	500.00
8	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	900.00	500.00
9	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	80.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,630.00</b>	<b>1,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >