

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE		Ref:	CS3/ASM22003726/Vty3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	11/05/2022	
	ATTN : HO WINNIE	<u> </u>		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SH 8353L	Veh. Inspected		GBJ 2612U
	Policy No.		Coverage (\$)		0.00
	Claim No.	S2M03Z4D	Excess (\$)		0.00
	Assign From	HO WINNIE	Assign Date		22/04/2022
2.	. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150 5MT	c.c		2982
	Engine No.	HIDDEN	Year of Reg.		2019
	Chassis No.	JTFAT35Y70K212644	Colour		SILVER
	Odometer	111653 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/75R15	YOKOHAMA		6 mm
	L/H Front Tyre	195/75R15	YOKOHAMA		6 mm
	R/H Rear Tyre	195/75R15	YOKOHAMA		6 mm
	L/H Rear Tyre	195/75R15	YOKOHAMA		6 mm
4.	Description of Damages				
	THE VEHICLE SUS PORTION.	SUSTAINED DAMAGES AT THE FRONT AND REAR			
5.	General Information				
	Accident Date	20/04/2022	Inspect Date /	Time	22/04/2022 (04:50 PM)
	Survey held at	LIFY SERVICES			
	1 KAKI BUKIT AVENUE 6 #01-56 AUTOBAY @ KAKI BUKIT SINGAPORE 417883				
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				

Report Ref No. CS3/ASM22003726/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser