

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB22003730/EYA3Q2**Date:** 11/04/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01

**Claimant Vehicle No :** SLM3773Y **Insured Vehicle No :** SMV9646H

Date of Loss: 10/04/2022 Nature of Claim: TP Claim No: MFL2022D0001866

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM3773Y**

Make & Model: BMW 218i, 1.5 CONVERTIBLE HID ABS NAV (A) Engine No: F0451566B38B15A

Reg. Date: 07/03/2017 (Man. Year: 2016) Chassis No: WBA1M32050V819741

Colour: Black Odometer: 70578 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,960.24	7,230.14	3,730.10	34.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,293.00	4,540.00	2,753.00	37.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,253.24</b>	<b>11,770.14</b>	<b>6,483.10</b>	<b>35.52</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,277.73	823.91	453.82	35.52
<b>Nett Amount (S\$)</b>	<b>19,530.97</b>	<b>12,594.05</b>	<b>6,936.92</b>	<b>35.52</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>12,961.50</b>		

INSPECTION

Date of Assignment: 12/04/2022

Date Inspected: 21/04/2022 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance  
Centre  
Singapore 159941

Estimated Period of Repair: 6.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2022)
<b>Parts:</b>	M1-COUPE	BMW 218I 1.5 CONVERTIBLE HID ABS NAV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLM3773Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*FRONT AXLE S	Not Necessary	1,363.10 FS	*- FS
3	1		*LH WISHBONE	Bent	272.50 FS	*272.50 FS
4	1		*RH WISHBONE	Not Necessary	272.50 FS	*- FS
5	1		*LH TENSION STRUT W/HYDRAULIC MOUNT	Bent	272.50 FS	*272.50 FS
6	1		*RH TENSION STRUT W/HYDRAULIC MOUNT	Not Necessary	272.50 FS	*- FS
7	1		*WHEEL HUB WITH BEARING FRT	N/S Necessary	974.00 FS	*487.00 FS
8	1		*FRT LH CARRIER	Bent	484.50 FS	*484.50 FS
9	1		*FRT RH CARRIER	Not Necessary	484.50 FS	*- FS
10	1		*FRT GUIDE SUPPORT	Not Necessary	239.00 FS	*- FS
11	1		*FRT SPRING STRUT	N/S Bent	626.70 FS	*313.35 FS
12	1		*RH TIE ROD	Not Necessary	298.15 FS	*- FS
13	1		*LH BALL JOINT	Bent	178.10 FS	*178.10 FS
14	1		*EXCH STEERING BOX ELECTR (ZF)	Bent	4,995.00 FS	*4,995.00 FS
15	1		*HEX NUT M10 CHROME FREE	Necessary	1.84 FS	*1.84 FS
16	1		*HEX SCREW WITH COLLAR M12X1.5X85	Necessary	8.45 FS	*8.45 FS
17	1		*HEXAGON SCREW WITH FLANGE M12X121	Necessary	12.90 FS	*12.90 FS
18	4		*SPHERICAL COLLAR SCREW M12X1.25X45	Necessary	32.20 FS	*32.20 FS
19	1		*HEXAGON SCREW WITH FLANGE M10X85	Necessary	7.10 FS	*7.10 FS
20	2		*COMBINATION NUT M14X1.5	Necessary	12.20 FS	*12.20 FS
21	1		*HEX NUT WITH FLANGE	Necessary	2.50 FS	*2.50 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)**      **10,960.24**      **7,230.14**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO MAKE GOOD FRONT BUMPER	New	1,275.00	0.00
2	TO RESPRAY FRONT BUMPER	New	1,038.00	0.00
3	TO REMOVE AND INSTALL FRONT SUSPENSION FOR INSPECTION AND REPLACE DAMAGED PARTS	New	2,655.00	2,522.00
4	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS	New	1,062.00	1,009.00
5	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	188.00	0.00
6	TO SUPPLY AND INSTALL BOTH FRONT ALLOY RIMS (TBA)	New	13.00	0.00
7	TO REPLACE ELECTROMECHANICAL POWER STEERING INCLUDING PROGRAM ,INTIALIZE STEERING COLUMN ADJUSTMENT AND CONDUCT CHECK FOR PROPER FUNCTION	New	885.00	841.00
8	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FORP PROPER FUNCTION ADJUSTMENT OF HEADLIGHTS	New	177.00	168.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,293.00</b>	<b>4,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >