

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003734/UQY3N2**Date:** 20/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00176092103

Claimant Vehicle No : SJC7876J**Insured Vehicle No :** SJS1850M

Date of Loss: 18/04/2022

Nature of Claim: TP

Claim No: SNM22D202655/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJC7876J**

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2960423

Reg. Date: 28/02/2008 (Man. Year: 2007)

Chassis No: ZNE100379819

Colour: Silver

Odometer: 385446 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,811.77	3,197.33	2,614.44	44.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	2,090.00	1,610.00	43.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,511.77	5,287.33	4,224.44	44.41
Approved Total (Overridden) (\$\$)		4,100.00		
Nett Amount (\$\$)	9,511.77	4,100.00	5,411.77	56.90

INSPECTION

Date of Assignment: 22/04/2022

Date Inspected: 22/04/2022 Inspected At:

Tick Hai Motor & Welding Services - Kaki Bukit (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC7876J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,246.28 FL	*468.10 FL
2	2		*REAR BUMPER SIDE RETAINER	Bent	101.78 FL	*101.78 FL
3	1		*SET REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	137.10 FL	*- FL
5	2		*TAILLAMP	Not Necessary	920.20 FL	*- FL
6	1		*REAR TAILGATE	Badly Dented	1,466.85 FL	*1,293.10 FL
7	1		*REAR TOYOTA LOGO	Necessary	68.50 FL	*68.50 FL
8	1		*REAR BOOT INNER LOCK	Dented/Jammed	197.53 FL	*197.53 FL
9	1		*REAR BOOT CATCH	Not Necessary	64.50 FL	*- FL
10	1		*REAR BOOT INNER TRIMBOARD	Deformed/Torn	302.51 FL	*302.51 FL
11	1		*SET REAR BOOT INNER TRIMBOARD CLIP	Necessary	50.00 FL	*50.00 FL
12	1		*REAR BOOT INNER TRIMBOARD PULL POCKET	Not Necessary	89.65 FL	*- FL
13	1		*REAR BOOT WEATHERSTRIP	Twisted	371.50 FL	*371.50 FL
14	1		*REAR NUMBER PLATE TOP GARNISH	Not Necessary	383.85 FL	*- FL
15	2		*REAR NUMBER PLATE LAMP	Not Necessary	163.10 FL	*- FL
16	1		*END PANEL	Badly Dented	605.85 FL	*605.85 FL
17	1		*END PANEL TOP GARNISH	Twisted	263.40 FL	*263.40 FL
18	2		*END PANEL STRUT	Not Necessary	95.60 FL	*- FL
19	1		*SET REAR WINDSCREEN MOULDING	Necessary	117.50 FL	*117.50 FL
20	1		*SET REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
21	1		*REVERSE CAMERA	Not Necessary	280.00 FS	*- FS
22	1		*END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
23	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,485.70	4,169.77
- List Item Discount on L Items 25.00/25.00% (S\$)	1,673.93	972.44
Total Parts (S\$)	5,811.77	3,197.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	80.00	20.00
2	TO REMOVE & REINSTALL REAR BUMPER SENSORS	New	120.00	50.00
3	TO TRANSFER REAR BOOT COMPONENTS FROM OLD BOOT TO NEW BOOT	New	120.00	60.00
4	TO TRANSFER REAR WINDSCREEN FROM OLD BOOT TO NEW BOOT	New	150.00	120.00
5	TO REMOVE & REINSTALL REAR INNER TRIMS,GARNISHES ETC TO FACILITATE REPAIR	New	250.00	80.00
6	TO APPLY ANTI RUSTING COATING ON NEW AND AFFECTED PANELS	New	200.00	60.00
7	TO REMOVE & REINSTALL REAR BOOT TOP SPOILER	New	80.00	0.00
8	TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,500.00	800.00
9	TO SPRAY PAINTING ON AFFECTED AREA	New	1,200.00	900.00
Gross Labour Cost (\$\$)			3,700.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >