

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003735/KVY3N2**Date:** 26/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00123252100
Claimant Vehicle No :	SMS2240G	Insured Vehicle No :	SKF6512M
Date of Loss:	16/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202702/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS2240G	Engine No:	3A92UJK3485
Make & Model:	MITSUBISHI SPACE STAR, 1.2 (A)	Chassis No:	MMBXTA03ALH000356
Reg. Date:	17/02/2020 (Man. Year: 2019)	Odometer:	66505 km
Colour:	Metallic Pearl White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/55R15	Rear Tyre Size:	175/55R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,385.40	1,253.70	2,131.70	62.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	485.00	1,065.00	68.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,935.40	1,738.70	3,196.70	64.77
+ GST 7.00/7.00% (\$\$)	345.48	121.71	223.77	64.77
Nett Amount (\$\$)	5,280.88	1,860.41	3,420.47	64.77

INSPECTION

Date of Assignment:	22/04/2022	
Date Inspected:	25/04/2022 Inspected At:	Fulco Autocare Pte Ltd (HQ) 176 SIN MING DRIVE #03-02 SIN MING AUTOCARE Singapore 575721
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2022)
Parts:	143	mitsubishi space star 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS2240G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP N/S	Serviceable	874.00 FL	*- FL
2	1		*HEADLAMP LOWER BRACKET N/S	Serviceable	68.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	488.00 FL	*432.00 FL
4	1		*FRONT BUMPER	Buckled	739.00 FL	*739.00 FL
5	3		*FRONT BUMPER CHROME MOULDING	Cracked (1 Pc only)	525.00 FL	*162.00 FL
6	2		*FRONT BUMPER SIDE RETAINER	Serviceable	136.00 FL	*- FL
7	1		*FRONT GRILLE	Serviceable	434.00 FL	*- FL
8	1		*FRONT GRILLE MITSUBISHI LOGO	Serviceable	66.00 FL	*- FL
9	1		*FRONT GRILLE CHROME GARNISH	Serviceable	246.00 FL	*- FL
10	12		*FRONT BUMPER CLIPS	Necessary	54.00 FS	*54.00 FS
11	8		*BONNET INSULATOR CLIPS	Not Necessary	36.00 FS	*- FS
12	6		*FRONT GRILLE CLIPS	Not Necessary	27.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,743.00	1,387.00
- List Item Discount on L Items 10.00/10.00% (\$)	357.60	133.30
Total Parts (\$)	3,385.40	1,253.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTIONS .TO PANEL BEAT ,RESHAPE ,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	800.00	250.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	15.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL	New	600.00	220.00
4	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			1,550.00	485.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >