



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7317R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BMPER - G4A	CUT	551.89	551.89
1	REAR BUMPER RE-INFORCEMENT	SERVICEABLE	378.32	-
1	REAR BUMPER LOWER COVER - BLACK	SCRATCHED	654.96	654.96
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	55.00	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER TOW COVER	SERVICEABLE	82.70	-
	LESS 25% DISCOUNT		-436.22	-307.21
			1,308.65	921.64
	<u>NETT ITEMS</u>			
1	REVERSE SENSOR (N)	CUT	135.70	135.70
	LESS 10% DISCOUNT		-13.57	-13.57
			122.13	122.13
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
			820.00	630.00
	GRAND TOTAL		2,300.78	1,673.77
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,673.77

Report Ref No. NS/INC22003737/Vqce2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.