



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3421M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER COVER	TO REPAIR SEE LABOUR	459.40	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	SCRATCHED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
1	ANTENNA SMARTKEY	SERVICEABLE	40.50	-
1	REAR BUMPER FOG LAMP	SERVICEABLE	201.50	-
1	LICENCE LAMP	SERVICEABLE	85.30	-
	LESS 20% DISCOUNT		-330.95	-94.65
			1,323.80	378.60
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR NUMBER PLATE WITH TRIM COVER (SN)	CRACKED	55.00	55.00
1	REAR BUMPER REVERSE SENSOR (SN)	CUT	180.00	180.00
			235.00	235.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER COVER.		400.00	350.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	CHECK ALL LIGHTING.		60.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			1,140.00	660.00
	<b>GRAND TOTAL</b>		<b>2,698.80</b>	<b>1,273.60</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,000.00</b>

Report Ref No. NS/INC22003739/Vtcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.