

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6673B

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------|-------------------------|------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER COVER | DENTED | 553.00 | 553.00 |
| 1 | REAR BUMPER LOWER COVER | DENTED | 228.00 | 228.00 |
| 1 | REAR BUMPER REINFORCEMENT | SERVICEABLE | 428.40 | - |
| 1 | REAR BUMPER BRACKET SIDE /RH | NECESSARY | 35.60 | 35.60 |
| 10 | REAR BUMPER CLIPS @\$2.20 | NECESSARY | 22.00 | 22.00 |
| 1 | BOOTLID EMBLEM I-40 | NECESSARY | 67.90 | 67.90 |
| 1 | BOOTLID EMBLEM CRDI | NECESSARY | 52.40 | 52.40 |
| 1 | REAR FENDER SHIELD RH | SERVICEABLE | 174.90 | - |
| 1 | TAIL LAMP RH | CRACKED | 697.80 | 697.80 |
| 1 | REAR FENDER AIR DUCT | SERVICEABLE | 51.60 | - |
| 1 | REAR WHEEL CAP | SERVICEABLE | 214.20 | - |
| 1 | REAR FENDER RH | TO REPAIR SEE LABOUR | 2,171.40 | - |
| | LESS 20% DISCOUNT | | -939.44 | -331.34 |
| | | | 3,757.76 | 1,325.36 |
| | NETT ITEMS | | | |
| 1 | REAR DOOR COMPORT APP (N) | NECESSARY | 80.00 | 80.00 |
| 1 | COMFORTDELGO/ TEL NUMBER STICKER (N) | NECESSARY | 60.00 | 60.00 |
| 1 | REVERSE SENSOR (N) | SERVICEABLE | 135.70 | - |
| | LESS 10% DISCOUNT | | -27.57 | -14.00 |
| | | | 248.13 | 126.00 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR DOOR ADVERTISMENT (SN) | NECESSARY | 100.00 | 100.00 |
| 1 | REAR FENDER ADVERTISEMENT (SN) | NECESSARY | 100.00 | 100.00 |
| 1 | REAR BUMPER ADVERTISMENT (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | REAR BUMPER MAT (SN) | NECESSARY | 50.00 | 50.00 |
| | | | 300.00 | 300.00 |



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

2,450.00

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|---------------|------------------------------|-------------------|
| | <u>LABOUR</u> | | | |
| | PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER RH. | | 980.00 | 560.00 |
| | SPRAY PAINTING CHARGE. | | 800.00 | 700.00 |
| | REMOVE/REFIX UPHOLSTERY | NOT NECESSARY | 90.00 | - |
| | CHECK LIGHTING. | | 60.00 | 30.00 |
| | TUFF KOTE | | 90.00 | 30.00 |
| | | | 2,020.00 | 1,320.00 |
| | GRAND TOTAL | | 6,325.89 | 3,071.36 |

Report Ref No. NS/INC22003740/Vtcn2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

(CONFIRMED)



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser