

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 4301M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	SCRATCHED	451.25	451.25
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	41.45	-
1	REAR BUMPER RETAINER LH	NECESSARY	55.80	55.80
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR WHEEL CAP LH	SCRATCHED	346.40	346.40
1	REAR DOOR LH	DENTED	2,147.90	2,147.90
1	REAR DOOR PROTECTOR LH	NECESSARY	166.20	166.20
1	ROCKER PANEL GARNISH LH	SCRATCHED	290.00	290.00
	LESS 20% DISCOUNT		-796.08	-787.79
			3,184.32	3,151.16
	SPECIAL NETT ITEMS			
1	REAR FENDER (PATROL ONLY) LH (SN)	NECESSARY	40.00	40.00
1	REAR DOOR APPS STICKER LH (SN)	NECESSARY	80.00	80.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			170.00	170.00
	<u>LABOUR</u>			
	PANEL BEATING - REAR FENDER ARCH LH.		800.00	700.00
	SPRAY PAINTING CHARGE.		1,200.00	750.00
	CHECK WIRINGS.		40.00	20.00
	TUFF KOTE.		80.00	30.00
	TRANSFER OF DOOR.		120.00	60.00
	R/I REVERSE SENSORS.		120.00	30.00
			2,360.00	1,590.00
	GRAND TOTAL		5,714.32	4,911.16





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,900.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC22003746/Vvcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser