



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 5067L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CUT	498.00	498.00
10	REAR BUMPER CLIPS @\$3.50	NECESSARY	35.00	35.00
1	REAR BUMPER O/S SIDE RETAINER	NECESSARY	29.00	29.00
3	REAR BUMPER O/S INNER SHIELD CLIPS @\$3.50	NOT NECESSARY	10.50	-
1	REAR O/S FENDER	TO REPAIR SEE LABOUR	1,806.00	-
6	REAR O/S FENDER INNER SHIELD CLIPS @\$3.50	NOT NECESSARY	21.00	-
1	REAR O/S DOOR	TO REPAIR SEE LABOUR	1,743.00	-
16	REAR O/S DOOR INNER TRIM BOARD CLIPS @\$5.50	NOT NECESSARY	88.00	-
1	REAR O/S LOWER ARM	NOT NECESSARY	239.00	-
1	REAR O/S SHOCK ABSORBER SHAFT	NOT NECESSARY	232.00	-
1	SET REAR O/S WHEEL BEARING & HUB	NOT NECESSARY	395.00	-
	LESS 20% DISCOUNT		-1,019.30	-112.40
			4,077.20	449.60
<u>SPECIAL NETT ITEMS</u>				
1	REAR O/S SPORT RIM (SN)	WARPED	650.00	500.00
1	REAR O/S WHEEL TYRE (195X65XR15)(SN)	SERVICEABLE	400.00	-
			1,050.00	500.00
<u>LABOUR</u>				
	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM.		50.00	20.00
	TO CHECK & ADJUST WHEEL BALANCING & WHEEL ALIGNMENT.		150.00	60.00
	TO REMOVE & REFIX REAR O/S SHOCK ABSORBER SHAFT, LOWER ARM, WHEEL BEARING & NECESSARY PARTS.	NOT NECESSARY	220.00	-
	TO REMOVE & REFIX CARPET, FLOOR MAT, REAR O/S FENDER INNER GARNISH, REAR O/S DOOR INNER TRIM BOARD COVER FOR REPAIR.		180.00	60.00
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT REAR O/S DOOR & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR O/S FENDER AND REAR O/S DOOR.		1,350.00	450.00

Report Ref No. CS/AGI22003757/Uqy3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		1,500.00	600.00
	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.	NOT NECESSARY	80.00	-
			3,530.00	1,190.00
GRAND TOTAL			8,657.20	2,139.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CS/AGI22003757/Uqy3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.