



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFB 2112R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER REAR (N)	DISTORTED	1,550.00	1,550.00
1	BUMPER CHROME MOULDING REAR (N)	NECESSARY	130.00	130.00
2	BUMPER SIDE MOULDING REAR @\$115.00 (N)	NECESSARY	230.00	230.00
2	BUMPER SIDE RETAINER REAR @\$95.00 (N)	NOT NECESSARY	190.00	-
	LESS 10% DISCOUNT		-210.00	-191.00
			1,890.00	1,719.00
	<u>LABOUR</u>			
	REMOVE & REPLACE ACCIDENT DAMAGED PARTS.		400.00	250.00
	SPRAY PAINTING ACCIDENT AFFECTED PARTS.		300.00	250.00
			700.00	500.00
	GRAND TOTAL		2,590.00	2,219.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,750.00

Report Ref No. CS/SMO22003758/Any3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.