

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003763/UPA3Q2**Date:** 28/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210056789
Claimant Vehicle No :	YN3878U	Insured Vehicle No :	SCF9388E
Date of Loss:	19/04/2022	Nature of Claim:	TP
		Claim No:	6340065903SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN3878U		
Make & Model:	MITSUBISHI FE83BE6SRDEA, 3.0 D (A)	Engine No:	4M42A91759
Reg. Date:	03/06/2013 (Man. Year: 2013)	Chassis No:	FE83BEA21060
Colour:	White	Odometer:	295331 km
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	7.00 R16	Rear Tyre Size:	7.00 R16 (D)
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,671.00	400.00	3,271.00	89.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	600.00	780.00	56.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,051.00	1,000.00	4,051.00	80.20
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,402.00		

INSPECTION

Date of Assignment:	25/04/2022	
Date Inspected:	25/04/2022 Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH FREEZER BOX STAINLESS PANEL (DENTED)	Not Consistent With The Impact	800.00 FS	*- FS
2	1		*REAR LH FREEZER BOX DOOR RUBBER (TORN)	Not Consistent With The Impact	650.00 FS	*- FS
3	1		*REAR LH TAIL LAMP (CRACKED)	Not Consistent With The Impact	85.00 F	*- F
4	1		*REAR LH CENTRE FREEZER BOX RUBBER (N/S)	Torn	600.00 FS	*400.00 FS
5	1		*REAR LH MUDGUARD	Repair	348.00 F	*- F
6	2		*REAR FREEZER SUPPORT RUBBER RH & LH (DAMAGED)	Not Consistent With The Impact	560.00 FS	*- FS
7	1		*REAR BUMPER (BENT)	Not Consistent With The Impact	600.00 FS	*- FS
8	1		*REAR NUMBER PLATE (METAL)	Not Necessary	28.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	3,671.00 400.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	40.00	0.00
2	REMOVE AND REFIX REAR FRIDGE DOOR COMPONENTS & WIPER MECHANISM	New	80.00	0.00
3	LABOR FOR PANEL BEATING ,CUT ,WELD STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	400.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	400.00	200.00
5	TO APPLY RUST PROOFING RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	0.00
Gross Labour Cost (\$\$)			1,380.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >