

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003764/VQY3Q2**Date:** 02/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00006262101

Claimant Vehicle No : SLJ7696B **Insured Vehicle No :** SLD3960X

Date of Loss: 19/04/2022 Nature of Claim: TP Claim No: SNM22D202716/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ7696B**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRY344254

Reg. Date: 27/12/2016 (Man. Year: 2016) Chassis No: MR053REH104561748

Colour: Blue Odometer: 267745 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16 Rear Tyre Size: 205/55Z R16

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,080.38	6,395.31	3,685.07	36.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	2,280.00	1,920.00	45.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,280.38	8,675.31	5,605.07	39.25
Approved Total (Overridden) (\$\$)		6,950.00		
(\$\$)	14,280.38	6,950.00	7,330.38	51.33
+ GST 7.00/7.00% (\$\$)	999.63	486.50	513.13	51.33
Nett Amount (\$\$)	15,280.01	7,436.50	7,843.51	51.33

INSPECTION

Date of Assignment: 22/04/2022

Date Inspected: 25/04/2022 Inspected At: Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Sep 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLJ7696B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	648.45 FL	*590.00 FL
2	2		*REAR BUMPER RETAINER	Necessary	264.66 FL	*200.00 FL
3	2		*REAR BUMPER REFLECTOR	Cracked	153.56 FL	*153.56 FL
4	2		*REAR BUMPER BRACKET	Necessary	240.46 FL	*240.46 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	439.45 FL	*439.45 FL
6	2		*REAR PDC SENSOR	Cut	448.58 FL	*250.00 FL
7	1		*BOOTLID	Dented	922.79 FL	*760.00 FL
8	2		*BOOTLID HINGE	Repair	153.78 FL	*- FL
9	1		*BOOTLID EMBLEM -LOGO	Necessary	69.81 FL	*69.81 FL
10	1		*BOOTLID EMBLEM -COROLLA	Necessary	58.65 FL	*58.65 FL
11	1		*BOOTLID EMBLEM -ALTIS	Necessary	61.16 FL	*61.16 FL
12	1		*BOOTLID OUTER CHROME GARNISH	Scratched	268.07 FL	*268.07 FL
13	1		*BOOTLID WEATHERSTRIP	Deformed	193.38 FL	*193.38 FL
14	2		*BOOTLID LAMP	Cracked	920.04 FL	*920.04 FL
15	1		*BOOTLID LOCK	Jammed	439.45 FL	*291.00 FL
16	1		*BOOTLID LOCK STRIKER	Repair	45.30 FL	*- FL
17	1		*BOOTLID INNER TRIM	Cut	400.73 FL	*285.00 FL
18	2		*TAILLAMP	Cracked	861.74 FL	*861.74 FL
19	2		*TAILLAMP PANEL	Repair	242.60 FL	*- FL
20	1		*END PANEL	Dented	781.44 FL	*700.00 FL
21	1		*END PANEL TOP GARNISH	Cut	266.09 FL	*266.09 FL
22	1		*REAR FENDER LH	Repair	1,264.78 FL	*- FL
23	1		*REAR FENDER INNER SHIELD LH	Cut	261.20 FL	*157.00 FL
24	2		*REAR FENDER INNER TRIM	Cut	725.34 FL	*448.00 FL
25	1		*REAR WHEEL HOUSE LH	Serviceable	314.20 FL	*- FL
26	1		*SPARE TYRE TOP BOARD	Bent	307.05 FL	*267.00 FL
27	1		*SPARE TYRE COMPARTMENT	Dented	893.31 FL	*780.00 FL
28	1		*REAR LH KNUCKLE ARM	Serviceable	407.00 FL	*- FL
29	1		*REAR LH KNUCKLE ARM BEARING	Serviceable	106.70 FL	*- FL
30	1		*REAR LH SHOCK ABSORBER	Serviceable	310.30 FL	*- FL
31	1		*REAR LH LOWER ARM	Serviceable	277.10 FL	*- FL
32	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
33	1		*SET BOOTLID TRIM CLIP	Necessary	50.00 FS	*30.00 FS
34	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	60.00 FS	*30.00 FS
35	1		*JOINT SEALANT	Necessary	150.00 FS	*60.00 FS
36	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
37	1		*REAR NUMBER PLATE	Broken	60.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,267.17	8,460.41
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,186.79	2,065.10
Total Parts (\$\$)	10,080.38	6,395.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	30.00
2	REMOVE & REFIT TRIMS & GARNISHES FOR REPAIR	New	200.00	100.00
3	REMOVE & REFIT BOOTLID ATTACHMENT	New	150.00	70.00
4	REMOVE & REPLACE REAR SENSOR	New	150.00	50.00
5	REMOVE & REFIT REAR WINDSCREEN	New	150.00	0.00
6	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	New	150.00	0.00
7	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	1,000.00
8	SRPAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,000.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	30.00
Gross Labour Cost (S\$)			4,200.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >