

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003769/UQY3N2**Date:** 19/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SNW00009562100

Claimant Vehicle No : SLL2161A**Insured Vehicle No :** PC6226X

Date of Loss: 21/04/2022

Nature of Claim: TP

Claim No: SNM22D202718/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLL2161A**

Make & Model: MAZDA 5, 2.0 (A)

Engine No: PE10436477

Reg. Date: 17/02/2017 (Man. Year: 2016)

Chassis No: JM6CW1071G0125112

Colour: Brown

Odometer: 62012 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,034.88	2,224.56	2,810.32	55.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	790.00	1,220.00	60.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,044.88	3,014.56	4,030.32	57.21
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	7,044.88	2,400.00	4,644.88	65.93

INSPECTION

Date of Assignment: 22/04/2022

Date Inspected: 25/04/2022

Inspected At:

Autobay Pte Ltd (kaki Bukit) (HQ)
1 KAKI BUKIT AVE 6, #02-11
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2022)
Parts:	M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL2161A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Badly Dented	1,304.40 FL	*1,304.40 FL
2	1		*FRONT DOOR HINGES RH	Not Necessary	44.50 FL	*- FL
3	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	86.40 FL	*86.40 FL
4	1		*FRONT DOOR INNER LOCK RH	Damaged/Shorted	467.10 FL	*467.10 FL
5	2		*FRONT DOOR INNER TRIM BOARD RH	Not Necessary	362.20 FL	*- FL
6	1		*FRONT DOOR OUTER HANDLE RH	Bent/Twisted	144.50 FL	*144.50 FL
7	1		*FRONT DOOR LOCK CYLINDER RH	Not Necessary	186.90 FL	*- FL
8	1		*FRONT DOOR FRAME BLACK GARNISH RH	Necessary	90.80 FL	*90.80 FL
9	1		*FRONT DOOR WINDOW CHANNEL MOULDING RH	Bent	43.10 FL	*43.10 FL
10	1		*FRONT DOOR WINDOW REGULATOR RH	Bent	185.80 FL	*185.80 FL
11	1		*FRONT DOOR WINDOW REGULATOR MOTOR RH	Shorted	296.10 FL	*296.10 FL
12	1		*FRONT WING MIRROR ASSEMBLY RH	Not Necessary	378.90 FL	*- FL
13	1		*CENTRE PILLAR	Repair	2,427.90 FL	*- FL
14	12		*FRONT BUMPER CLIPS	Not Necessary	54.00 FS	*- FS
15	8		*FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	36.00 FS	*- FS
16	2		*FRONT DOOR STICKER	Necessary	130.00 FS	*130.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,238.60	2,748.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,203.72	523.64
Total Parts (\$\$)	5,034.88	2,224.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECKING ELECTRICAL WIRING AND CHECK FUNCTIONS	New	60.00	20.00
2	TO REMOVE, REFIX FRONT DOOR COMPONENTS AND REPLACE FRONT DOOR, CHECK ALIGNMENT	New	400.00	60.00
3	TO RESPRAY UNDERCOATING/RUST PROOFING	New	100.00	30.00
4	TO RESPRAY PAINTING & ETC	New	750.00	280.00
5	PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS	New	700.00	400.00
Gross Labour Cost (\$)			2,010.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >