

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003773/AYA3Q2**Date:** 19/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900172684
Claimant Vehicle No :	SJU7000A	Insured Vehicle No :	SMP6488Z
Date of Loss:	19/04/2022	Nature of Claim:	TP
		Claim No:	9932471300SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU7000A	Engine No:	27186030023899
Make & Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Chassis No:	WDD2073472F031161
Reg. Date:	12/08/2011 (Man. Year: 2009)	Odometer:	163238 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/30 R19	Rear Tyre Size:	275/30 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,169.00	8,784.60	6,384.40	42.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,840.00	1,110.00	37.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,119.00	10,624.60	7,494.40	41.36
Approved Total (Overridden) (S\$)		8,500.00		
Nett Amount (S\$)	18,119.00	8,500.00	9,619.00	53.09
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
Nett Liability (S\$)		9,200.00		

INSPECTION

Date of Assignment:	20/04/2022	
Date Inspected:	20/04/2022 Inspected At:	ADVANCE AUTO GARAGE (23 KAKI BUKIT) (HQ) 25 KAKI BUKIT AVE 4 #04-01 VICOM KAKI BUKIT Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,631.00 F	*1,631.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Damaged	170.00 F	*170.00 FL
4	1		*REAR BUMPER LOWER GARNISH	Distorted	365.00 F	*365.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	655.00 F	*655.00 FL
6	1		*REAR BUMPER CENTRE GUIDE	Creased	215.00 F	*215.00 FL
7	1		*REAR BUMPER TOW COVER	Missing	35.00 F	*35.00 FL
8	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,020.00 F	*510.00 FL
9	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	485.00 F	*- FL
10	1		*REAR END PANEL	Repair	1,023.00 F	*- FL
11	1		*REAR END PANEL TOP GARNISH	Cracked	275.00 F	*275.00 FL
12	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
13	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FL
14	2		*TAILLAMP	Cracked	1,350.00 F	*1,350.00 FL
15	2		*TAILLAMP LOWER BRACKET	Cracked	130.00 F	*130.00 FL
16	1		*BOOTLID	Dented	1,835.00 F	*1,835.00 FL
17	1		*BOOTLID LOCK	Damaged	325.00 F	*325.00 FL
18	1		*BOOTLID WEATHERSTRIPE	Necessary	298.00 F	*298.00 FL
19	2		*BOOTLID REFLECTOR	Not Necessary	1,100.00 F	*- FL
20	1		*REAR EXHAUST PIPE	Bent	3,860.00 FS	*1,700.00 FS
21	2		*REAR EXHAUST MOUNTING	Not Necessary	84.00 F	*- FL
22	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	183.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,169.00	9,564.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	779.40
Total Parts (\$\$)	15,169.00	8,784.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	750.00
2	SPRAY PAINTING	New	1,000.00	750.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO SPRAY TUFF COAT	New	150.00	30.00
6	TO REMOVE UPHOLSTERY	New	150.00	50.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
8	TO REMOVE EXHAUST PIPE	New	150.00	120.00
			Gross Labour Cost (S\$)	2,950.00
				1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >