

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003781/TVCE2

Date: 20/09/2022

REFERENCE

Insured/Claimant:	YONG CHUN SEK	Policy No:	7210154945		
Date of Loss:	19/04/2022	Nature of Claim:	OD	Claim No:	3363913188SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE1970L	Engine No:	DEM034228
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF52MA062405
Reg. Date:	29/12/2021 (Man. Year: 2021)	Odometer:	7364 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$194,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,572.00	13,746.72	15,825.28	53.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,172.00	3,122.00	2,050.00	39.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,744.00	16,868.72	17,875.28	51.45
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	33,144.00	15,268.72	17,875.28	53.93
+ GST 7.00/7.00% (S\$)	2,320.08	1,068.81	1,251.27	53.93
Nett Amount (S\$)	35,464.08	16,337.53	19,126.55	53.93

INSPECTION

Date of Assignment:	25/04/2022		
Date Inspected:	22/04/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	2		*SPREADER RIVET	Necessary	4.00 FS	*2.88 FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Deformed	293.00 FS	*234.00 FS
5	1		*RADIATOR GRILLE	Cut	1,881.00 FS	*1,504.80 FS
6	1		*RADIATOR GRILLE COVER CAP	Not Necessary	141.00 FS	*- FS
7	1		*RADIATOR GRILLE BRACKET	Not Necessary	19.00 FS	*- FS
8	1		*RADIATOR GRILLE SECURING PLATE	Not Necessary	12.00 FS	*- FS
9	1		*FRONT CAMERA	Not Necessary	1,261.00 FS	*- FS
10	2		*FRONT PARKING AID SENSOR - INNER	Not Necessary	530.00 FS	*- FS
11	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	163.00 FS	*130.40 FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
14	2		*FRONT BUMPER SUPPORT - LH / RH	Necessary	64.00 FS	*51.04 FS
15	4		*POP RIVET	Necessary	4.00 FS	*2.88 FS
16	1		*FRONT BUMPER LOCK CARRIER BRACKET	Craked	154.00 FS	*122.80 FS
17	1		*FRONT BUMPER TOP COVER	Deformed	143.00 FS	*114.00 FS
18	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
19	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
20	1		*BONNET	Bent	3,491.00 FS	*2,792.80 FS
21	1		*BONNET ATTACHMENT PARTS	Not Necessary	128.00 FS	*- FS
22	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
23	2		*BONNET STRIKER - LH / RH	Not Necessary	112.00 FS	*- FS
24	2		*BONNET LOCK	Not Necessary	455.00 FS	*- FS
25	1		*HEADLIGHT MATRIX BEAM - LH / RH	O/s cracked	16,344.00 FS	*6,537.60 FS
26	1		*RADIATOR AIR GUIDE INNER / OUTER - LH	Inner Deformed	55.00 FS	*14.64 FS
27	1		*RADIATOR AIR GUIDE INNER / OUTER - RH	Inner Deformed	55.00 FS	*14.64 FS
28	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
29	1		*SUNDRIES	Necessary	400.00 FS	*27.04 FS
30	1		*BONNET BOWDEN CABLE-CENTER	Distorted	64.00 FS	*50.56 FS
			(Supplementary)			

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 29,572.00 13,746.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY, FRONT PARKING AID AND CAM	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE (TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT INSTEAD OF BOTH HEADLIGHTS)	New	700.00	350.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH FRONT HEADLIGHTS. INSPECT LOCK CARRIER FOR DAMAGES. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	1,700.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,172.00	3,122.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >