



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 4752R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER LH (CONSISTENT)	BUCKLED	899.00	560.00
1	FRONT FENDER INNER SHIELD LH (CONSISTENT)	NOT NECESSARY	133.00	-
1	WING MIRROR LH (CONSISTENT)	DISTORTED	1,022.00	600.00
	LESS 10% DISCOUNT		-205.40	-116.00
			1,848.60	1,044.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT FENDER INNER SHIELD CLIP (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
			40.00	-
	<u>LABOUR</u>			
	CHECK WIRING AND LIGHTNING SYSTEM.		100.00	30.00
	PANEL BEATING ON AFFECTED AND RENEW DAMAGED PARTS.		500.00	200.00
	SPRAY PAINTING ON AFFECTED AREAS.		600.00	400.00
	APPLY ANTI RUST ON AFFECTED AREAS.		100.00	60.00
			1,300.00	690.00
	GRAND TOTAL		3,188.60	1,734.00
RECOMMENDED COST OF REPAIRS				1,734.00

Report Ref No. CS/ASM22003783/Gny3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.