

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4213B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	2,707.70	-
1	REAR DOOR RH	DENTED	2,201.10	2,201.10
1	ROCKER PANEL GARNISH RH	TO REPAIR SEE LABOUR	732.80	-
1	REAR WHEEL CAP RH	SCRATCHED	217.20	217.20
	LESS 20% DISCOUNT		-1,171.76	-483.66
			4,687.04	1,934.64
NETT ITEMS				
1	FRONT DOOR COMFORTDELGRO RH (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS RH (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
LABOUR				
	PANEL BEATING-REAR FENDER RH ETC.INCLUSIVE OF THE REPAIR OF FRONT DOOR RH AND ROCKER PANEL GARNISH RH.		800.00	560.00
	SPRAY PAINTING CHARGE-REAR BUMPER ETC.		1,200.00	1,000.00
	TRANSFER OF DOORS.		240.00	120.00
	WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			2,360.00	1,680.00
GRAND TOTAL			7,186.54	3,754.14
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,000.00

Report Ref No. NS/INC22003786/Vtcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.