

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP19100012

Date: 29 NOV 2019

Haszren Hassan

c/o D's Graffiti Concepts Pte Ltd

10 ang mo kio ind park 2A

Amk autopoint #03-13

Singapore 568047

THIRD PARTY SURVEY

ACCIDENT OCCURED ON 30 October 2019

Workshop Name and Address

D's Graffiti Concepts Pte Ltd

10 ang mo kio ind park 2A

Amk autopoint #03-13

Singapore 568047

As per your instruction dated

04 nov 2019

with regard to the above matter.

We have carried out a physical inspection on the said

SKN3080U

We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SKN3080U

Engine No : VEDA01017

Model : TOYOTA ALPHARD 2.4

Mileage : n.a km

Year / Capacity : Oct 2007 / 2362 cc

Colour : Metallic Silver

Chassis No : ANH100184299

2. TYRES CONDITION

| | <u>Size</u> | <u>Made</u> | <u>Balance</u> | <u>Rim</u> |
|-------------|-------------|-------------|----------------|------------|
| FRONT O/S : | 195/50/R15 | Bridgeston | 7.00 mm | Sport |
| REAR O/S : | 195/50/R15 | Bridgeston | 7.00 mm | Sport |
| FRONT N/S : | 195/50/R15 | Bridgeston | 7.00 mm | Sport |
| REAR N/S : | 195/50/R15 | Bridgeston | 7.00 mm | Sport |

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear side portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 05 working days to complete

5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SKN3080U

SPARE PARTS

| QTY | PARTS DESCRIPTION | CONDITION | Workshop Estimation (S\$) | Our Revised Estimation (S\$) |
|-------------------|------------------------------|----------------|---------------------------|------------------------------|
| <i>List Items</i> | | | | |
| 1 pc | Tail lamp | Cracked | \$ 748.90 | \$ 748.90 |
| 1 pc | Tail lamp sealant | necessary | \$ 80.00 | \$ 80.00 |
| 2 pcs | Tail lamp clips | necessary | \$ 51.60 | \$ 51.60 |
| 1 pc | Rear bumper upper | bend/deformed | \$ 1,808.00 | \$ 1,808.00 |
| 1 pc | Rear bumper upper cover (LH) | bend/deformed | \$ 310.00 | \$ 310.00 |
| 1 pc | Rear bumper side retainer | distorted | \$ 122.00 | \$ 122.00 |
| 1 pc | Rear bumper side attachment | bent/distorted | \$ 85.00 | \$ 85.00 |
| 1 pc | Rear bumper reflectors | deformed | \$ 135.00 | \$ 135.00 |
| 10 pcs | Rear bumper clips | necessary | \$ 80.00 | \$ 80.00 |
| 1 pc | Rear end panel | dent/distorted | \$ 907.50 | \$ 907.50 |
| 1 pc | Rear fender | distorted | \$ 1,582.50 | \$ 1,582.50 |
| Parts Sub-Total | | | \$ 5,910.50 | \$ 5,910.50 |
| Discount 25.00% | | | \$ 1,477.63 | \$ 1,477.63 |
| | | | \$ 4,432.88 | \$ 4,432.88 |

Vehicle Number : SKN3080U

SPARE PARTS

| QTY | PARTS DESCRIPTION | CONDITION | Workshop Estimation (S\$) | Our Revised Estimation (S\$) |
|---------------------------|---------------------------------|------------------------|---------------------------|------------------------------|
| <i>Special Nett Items</i> | | | | |
| 1 set | Rear bumper parking sensor | electronically shocked | \$ 280.00 | \$ 250.00 |
| 1 pc | Rear bumper parking sensor wire | open circuit | \$ 180.00 | \$ 180.00 |
| Special Nett Sub-Total | | | \$ 460.00 | \$ 430.00 |
| Spare Parts Total | | | \$ 4,892.88 | \$ 4,862.88 |

LABOUR COST

| S/No | JOB DESCRIPTIONS | Workshop Estimation (S\$) | Our Revised Estimation (S\$) |
|------|---|---------------------------------|------------------------------------|
| | Spare PartsTotal c/f | \$ 4,892.88 | \$ 4,862.88 |
| 1 | To tuff coat affected areas | \$ 150.00 | \$ 120.00 |
| 2 | To respray affected areas | \$ 1,800.00 | \$ 1,600.00 |
| 3 | To renew damaged parts, straighten and repair rear fender inner, rear chassis member and aligned all parts | \$ 1,600.00 | \$ 1,400.00 |
| 4 | To check and reconnect snap wiring | \$ 150.00 | \$ 120.00 |
| 5 | To remove and replace reverse sensor | \$ 180.00 | \$ 150.00 |
| | Total | \$ 8,772.88 | \$ 8,252.88 |


The repairer has agreed to undertake the repair under a Lump
Sum Basis. We have further adjusted the amount to a Lump
Sum Repair of :

\$ 6,600.00



Fong Kok Heng
Qualified Appraiser

AUTOMA




SURVEY


AUTOMOTIVE SURVEY



AUTOMOTIVE SURVEY



★ AUTOMOTIVE



★ AUTOMOTIVE




★ SURVEY


AUTOMOTIVE



AUTOMOTIVE



URVEX



AUTOMAT
SURVEY

AUTOMAT
SURVEY



AUTOMAT
SURVEY

