

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 3080U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL LAMP	CRACKED	748.90	480.10
1	TAIL LAMP SEALANT	NOT NECESSARY	80.00	-
2	TAIL LAMP CLIPS	NOT NECESSARY	51.60	-
1	REAR BUMPER UPPER	BENT / DEFORMED	1,808.00	1,768.00
1	REAR BUMPER UPPER COVER (LH)	BENT / DEFORMED	310.00	263.50
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	122.00	-
1	REAR BUMPER SIDE ATTACHMENT	NOT NECESSARY	85.00	-
1	REAR BUMPER REFLACTORS	DEFORMED	135.00	89.10
10	REAR BUMPER CLIPS	NECESSARY	80.00	43.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	907.50	-
1	REAR FENDER	TO REPAIR SEE LABOUR	1,582.50	-
	LESS 25% DISCOUNT		-1,477.63	-660.93
			4,432.87	1,982.77
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER PARKING SENSOR (SN)	NOT NECESSARY	280.00	-
1	REAR BUMPER PARKING SENSOR WIRE (SN)	NOT NECESSARY	180.00	-
			460.00	-
	<u>LABOUR</u>			
	TO TUFF COAT AFFECTED AREAS.		150.00	40.00
	TO RESPRAY AFFECTED AREAS.		1,800.00	600.00
	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR REAR FENDER INNER, REAR CHASSIS MEMBER AND ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR FENDER.		1,600.00	800.00
	TO CHECK AND RECONNECT SNAP WIRING.		150.00	30.00
	TO REMOVE AND REPLACE REVERSE SENSOR.		180.00	40.00
			3,880.00	1,510.00
	GRAND TOTAL		8,772.87	3,492.77

Report Ref No. CS/LAW22003788/Dvy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/LAW22003788/Dvy3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser