

## **PRIORITY SERVICES**

Insurance Loss Adjusters and Motor Appraisers Blk 779 Yishun Avenue 2 #01-1545 Singapore 760779

Tel: 6293 4822 Fax: 6296 3283 E-mail: admin@priorityservices.sg

Messrs.

Sompo Insurance Pte Ltd

50 Singapore Land Tower

#05-01/06 Raffles Place

Singapore 048623

Bill No : DN/00189/20

Date

: 29/1/2020

Dr.

To

Survey Fee

(S\$):

200.00

Photographs

(S\$):

Transport

( . )

Resurvey

(S\$): (S\$):

Miscellaneous

(S\$):

Services rendered including photographs and transport charges

(S\$):

200.00

Our Reference

: TP-0133/01/20

Insured

: FBL 409 T

Date Of Accident

: 30/10/2019

Policy / Cert. No.

: Paper Survey

Your Claim No

: CMTD1905127

Vehicle

: Toyota Alphard 2.4 (A) - SKN 3080 U

Dollars

: Two Hundred ONLY

For PRIORITY SERVICES

E & O.E.



## PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers Blk 779 #01-1545 Yishun Ave 2 Singapore 760779 Tel: 62934822 Fax: 62963283 E-mail: admin@priorityservices.sg

Date:

29 January 2020

Your Ref:

CMTD1905127

Our Ref:

TP-0133/01/20

Motor Claims Department M/s. Sompo Insurance Pte. Ltd. 50 Raffles Place #05-01/06 Singapore Land Tower Singapore 048623

Attention: Mr. Gnoh Pau Loong

Dear Sir,

Inspection of 2007 Toyota Alphard 2.4 (A)

Registration No.: SKN 3080 U Odometer Reading: 561306 km Chassis No.: ANH100184299

We refer to your instructions to us to conduct a paper survey of the above vehicle. A prerepair survey was conducted on 05-11-2019 and resurvey after repairs on 08-11-2019. The repairer did not arrange for survey of dismantled parts.

The following documents were received: -

- 1) Copy of survey report by M/s. Automax Survey
- 2) 26 copies of photos depicting damages sustained by SKN 3080 U
- 3) Accident reports by drivers of SKN 3080 U and FBL 409 T

The vehicle sustained rear LHS damages during an accident on 30-10-2019.

Repair cost submitted was \$6,600.00 lump-sum.

We append below our findings: -

Replacement of Parts		Revised Amount		Our Recommendation		
lpc.	Tail lamp	\$	748.90	\$	464.00	
lpc.	Tail lamp sealant - not necessary		80.00		_	
2pcs.	Tail lamp clips – not necessary		51.60			
lpc.	Rear bumper upper		1,808.00		1,654.00	
lpc.	Rear bumper upper cover LH		310.00		194.40	
lpc.	Rear bumper side retainer		122.00		83.30	
lpc.	Rear bumper side attachment (side garnish)		85.00		85.00	

1pc. 10pcs. 1pc.	Rear bumper reflectors Rear bumper clips Rear end panel – mostly old damage/repairable	\$	135.00 80.00 907.50	\$	99.60 45.00	
lpc.	Rear fender – scratched/repairable		1,582.50		-	
	Less 25%	\$	5,910.50 1,477.62	\$	2,625.30 656.32	
		\$	4,432.88	\$	1,968.98	
Special	Nett Items:-					
1set	Rear bumper parking sensor – serviceable	\$	250.00	\$	-	
lpc.	Rear bumper parking sensor wire – serviceable		180.00		-	
	Total For Parts:-	\$	4,862.88	\$	1,968.98	
Labour Charges:-						
To tuff coat affected areas.		\$	120.00	\$	90.00	
To respray affected areas.			1,600.00		800.00	
To renew damaged parts, straighten and repair rear fender, end panel and sliding door.			1,400.00		600.00	
To check and reconnect wiring.			120.00		30.00	
To remove and refit reverse sensor.			150.00		50.00	
	Total:-	\$	8,252.88	\$	3,538.98	
Lump-sum repairs:		\$	6,600.00	\$	2,800.00	

Estimated period of repairs: 4 working days

Pre-accident Market Value : About \$ 56,000.00 COE rebate : \$ 39,794.00

Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully

PRIORITY SERVICES

JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA

Motor Appraiser

Surveyed by:-

JEFFREY ONG

Motor Appraiser