

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22003789/KTY3N2**Date:** 05/05/2022**REFERENCE**

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP315686
Claimant Vehicle No :	SLH9033L	Insured Vehicle No :	SKX7398A
Date of Loss:	22/04/2022	Nature of Claim:	TP
		Claim No:	MPC03359

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH9033L	Engine No:	1ZRY309564
Make & Model:	TOYOTA COROLLA, 1.5 (A)	Chassis No:	MR053REH104553561
Reg. Date:	23/11/2016 (Man. Year: 2016)	Odometer:	135591 km
Colour:	Metallic Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Michelin 2 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 2 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,841.10	655.15	2,185.95	76.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	720.00	1,580.00	68.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,141.10	1,375.15	3,765.95	73.25
Approved Total (Overridden) (S\$)		1,100.00		
Nett Amount (S\$)	5,141.10	1,100.00	4,041.10	78.60

INSPECTION

Date of Assignment:	25/04/2022	Poon Siang Seow (HQ)
Date Inspected:	27/04/2022	Inspected At: 160 Sin Ming Drive, #05-13 Sin Ming AutoCity
Estimated Period of Repair:	3.0 days	Singapore 575722

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2022)
Parts:	143	TOYOTA COROLLA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH9033L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Deformed	596.50 F	*540.20 FL
2	2		*REAR BUMPER RETAINER	Serviceable	131.60 F	*- FL
3	1		*REAR BUMPER REFLECTOR	Serviceable	45.00 F	*- FL
4	1		*REAR FENDER LEFT	Repair	860.00 F	*- FL
5	1		*REAR W/S MOULDING	Not Necessary	108.00 F	*- FL
6	1		*TYRES	Serviceable	250.00 F	*- FL
7	1		*WHEEL RIM SPORT	Dented/Scratched	850.00 FS	*250.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					2,841.10	790.20
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	135.05
Total Parts (\$\$)					2,841.10	655.15
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING	New	80.00	0.00
2	PANEL BEATING	New	990.00	320.00
3	SPRAY PAINTING	New	880.00	400.00
4	TO REMOVE AND REFIT REAR W/S AND CUSHION	New	350.00	0.00
Gross Labour Cost (\$\$)			2,300.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >