

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20013447/TGA3Q2-1**Date:** 06/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070159022
<b>Claimant Vehicle No :</b>	SHA3434L	<b>Insured Vehicle No :</b>	GBJ183D
Date of Loss:	05/12/2020	Nature of Claim:	TP
		Claim No:	6752158969SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA3434L</b>	Engine No:	2ZR2G76775
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FUX03091260
Reg. Date:	15/04/2020 (Man. Year: 2020)	Odometer:	60103 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,378.37	773.85	1,604.52	67.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	780.00	220.00	22.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,378.37</b>	<b>1,553.85</b>	<b>1,824.52</b>	<b>54.01</b>
<b>+ GST 7.00/7.00% (S\$)</b>	236.49	108.77	127.72	54.01
<b>Nett Amount (S\$)</b>	<b>3,614.86</b>	<b>1,662.62</b>	<b>1,952.24</b>	<b>54.01</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$126.47/day) (S\$)</b>		252.94		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>2,023.05</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,000.00</b>		

INSPECTION

Date of Assignment:	07/12/2020	
Date Inspected:	07/12/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL -FENDER RH	Bent	945.30 FL	*945.30 FL
2	1		*LAMP ASSY -HEAD	Not Necessary	1,993.65 FN	*- FN
3	1		*EMBLEM -BLUE DRIVE	Necessary	86.50 FL	*86.50 FL
4	1		*BRACKET -FR BUMPER	Not Necessary	12.00 FN	*- FN
F=Franchise part. L=ListItemDisc. N=NettItemDisc.						
Sub Total (\$)					3,037.45	1,031.80
- List Item Discount on L Items 25.00/25.00% (\$)					257.95	257.95
- Nett Item Discount on N Items 20.00/20.00% (\$)					401.13	0.00
Total Parts (\$)					2,378.37	773.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT CHARGE	New	500.00	400.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,000.00</b>	<b>780.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >