

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003796/UNY3Q2**Date:** 11/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00145202101

Claimant Vehicle No : SLW6413P **Insured Vehicle No :** GBC9101T

Date of Loss: 17/04/2022 Nature of Claim: TP Claim No: SNM22D202647/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW6413P**

Make & Model: MAZDA 3, 1.5 (A) Engine No: P520498848

Reg. Date: 26/02/2018 (Man. Year: 2018) Chassis No: JM6BN22A8J0208585

Colour: Red Odometer: 57537 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,052.40	3,156.10	896.30	22.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,670.00	2,820.00	1,850.00	39.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,722.40	5,976.10	2,746.30	31.49
+ GST 7.00/7.00% (S\$)	610.57	418.33	192.24	31.49
Nett Amount (S\$)	9,332.97	6,394.43	2,938.54	31.49

INSPECTION

Date of Assignment: 10/07/2022

Date Inspected: 28/04/2022 Inspected At: Trans Eurokars Pte Ltd (Ubi)
5 Ubi Close
Singapore 408605

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2022)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW6413P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	1,128.60 F	*1,128.60 F
2	1		*BRACKET CENTER REAR BUMPER	Necessary	5.40 F	*5.40 F
3	1		*REINFORCEMENT REAR	Dented	564.20 F	*564.20 F
4	1		*RETAINER LH REAR	Bent	33.60 F	*33.60 F
5	1		*RETAINER RH REAR	Bent	33.60 F	*33.60 F
6	1		*COVER LH TOWING HOOK REAR	Missing	16.50 F	*16.50 F
7	1		*COVER RH TOWING HOOK REAR	Not Necessary	17.10 F	*- F
8	4		*RIVET	Necessary	18.00 F	*18.00 F
9	4		*FASTENER	Necessary	12.00 F	*12.00 F
10	4		*GROMMET SCREW	Necessary	10.80 F	*10.80 F
11	1		*TRUNK LID	Dented / Cracked	1,005.30 F	*1,005.30 F
12	1		*LAMP TRUNK LID LH	Not Necessary	278.30 F	*- F
13	1		*GASKET RH LAMP TRUNK LID	Necessary	22.00 F	*22.00 F
14	1		*GASKET LH LAMP TRUNK LID	Necessary	22.00 F	*22.00 F
15	2		*FASTENER	Necessary	12.40 F	*12.40 F
16	2		*GROMMET SCREW -R COMB	Necessary	6.60 F	*6.60 F
17	1		*TAIL LAMP LH	Not Necessary	500.90 F	*- F
18	1		*GASKET RH TAIL LAMP	Necessary	22.00 F	*22.00 F
19	1		*GASKET LH TAIL LAMP	Necessary	22.00 F	*22.00 F
20	1		*ORNAMANT MAZDA 3	Necessary	56.10 F	*56.10 F
21	1		*ORNAMENT SKYACTIV	Necessary	66.80 F	*66.80 F
22	1		*MASCOT REAR	Necessary	78.20 F	*78.20 F
23	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
24	1		*NUMBER PLATE	Serviceable	70.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,052.40** **3,156.10**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND TRUNK LID	New	1,500.00	990.00
2	TO RESPRAY REAR BUMPER AND TRUNK LID	New	1,400.00	1,260.00
3	TO TRANSFER REVERSE SENSORS }	New	660.00	300.00
4	TO TRANSFER REVERSE CAMERA }	New	660.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	120.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	250.00	150.00
Gross Labour Cost (\$)			4,670.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >