

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003798/AYA3Q2**Date:** 12/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100298062-10
Claimant Vehicle No :	SMQ200X	Insured Vehicle No :	SKG663U
Date of Loss:	04/04/2022	Nature of Claim:	TP
		Claim No:	9391933234SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ200X	Engine No:	2AZC403370
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR500072554
Reg. Date:	30/06/2008 (Man. Year: 2008)	Odometer:	152410 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,273.20	1,030.95	242.25	19.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	700.00	600.00	46.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,573.20	1,730.95	842.25	32.73
Approved Total (Overridden) (S\$)		1,350.00		
Nett Amount (S\$)	2,573.20	1,350.00	1,223.20	47.54
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	22/04/2022	
Date Inspected:	22/04/2022	Inspected At: Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT BUMPER ASSY	Defaced	982.10 FL	*982.10 FL	
2	5		*FRT BUMPER CLIPS	Necessary	28.90 FL	*28.90 FL	
3	1		*FRT BUMPER SIDE HOLDER RH	Necessary	151.20 FL	*78.00 FL	
4	1		*FRT FENDER INNER LINER RH	Torn	285.60 FL	*285.60 FL	
5	1		*FRT BUMPER FOGLAMP RH	Not Necessary	249.80 FL	*- FL	
					Sub Total (\$)	1,697.60	1,374.60
					- List Item Discount on L Items 25.00/25.00% (\$)	424.40	343.65
					Total Parts (\$)	1,273.20	1,030.95

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORK & WHERE CONSISTENT TO THE ACCIDENT	New	500.00	300.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	800.00	400.00
			Gross Labour Cost (S\$)	700.00
			1,300.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >